LUNMAR BOAT LIFTS ALUMINUM MOUNT INSTALLATION GUIDE

3000# SLING KIT AND CRADLE KIT 4000# SLING KIT AND CRADLE KIT 6000# SLING KIT AND CRADLE KIT

READ ALL INSTRUCTIONS BEFORE STARTING

THE LUNMAR 3000, 4000, AND 6000 BASIC INSTALLATION ARE THE SAME. THE 3000 AND 4000 WORK BASED ON A SINGLE LINE PULL AND THE 6000 WORKS BASED ON A DOUBLE LINE PULL. THE OVERHEAD INSTALLATION OF THESE KITS ARE THE SAME. EXCEPT ON THE 3000 AND 4000, THE CABLE CONNECTS DIRECTLY TO THE SLING OR CRADLE BEAM AND ON THE 6000 IT PASSES THROUGH A PULLEY AND THEN BACK UP TO DEADMAN OFF ON AN OVERHEAD BEAM. LUNMAR KITS ARE DESIGNED FOR A 2" SCHEDULE 40 GALVANIZED PIPE TO RUN DOWN THE CENTER AND PARALLEL TO THE BOAT, WHICH IS SUSPENDED THE OVERHEAD ALUMINUM BEAMS THAT PERPENDICULAR TO THE BOAT BY STRAP BEARINGS. THE BEAMS, WHICH THE KIT ATTACH TO, ARE USUALLY 10' TO 12' APART DEPENDING ON THE LENGTH OF THE BOAT. THE DISTANCE BETWEEN THE 560 PULLEYS ARE 10' IF THE BOAT IS 8 1/2' WIDE.

FOLLOW THESE STEPS FIRST:

- PULL THE BOAT INTO THE BOAT SLIP.
- ■THE AFT ALUMINUM BEAM SHOULD BE LOCATED 1' TO 2' FROM TRANSOM.
- ■THE NEXT BEAM SHOULD BE LOCATED ABOVE THE BOAT WHERE YOU WOULD WANT THE FRONT SLING TO HIT THE BOAT. USUALLY 10' TO 12'.

LUNMAR ALUMINUM MOUNT KITS PARTS LIST

3000# Capacity

Sling Kit Parts List:

O(1) AMS 3000 (Motor/Gearplate/Switch/GFI) O(4) Thimbles

O(4) 102G Strap Bearings O(4) ½" x 1½" Bolts/Nuts/Locks/Flats

O(4) 560 Aluminum Pulleys
O(8) ¼" Cable Clamps
O(8) ½" Cable Clamps
O(2) 4" x 14' Nylon Slings

O(2) 6" x 12'6" Aluminum Overhead Beams

Cradle Kit Parts List:

O(1) AMS 3000 (Motor/Gearplate/Switch/GFI) O(4) ½" x 1½" Bolts/Nuts/Locks/Flats
O(4) 102G Strap Bearings O(8) ½" x 6" Bolts/Nuts/Locks/Flats

O(4) 560 Aluminum Pulleys O(8) ½" x 3" Bolts/Nuts/Locks/Flats

O(80) Feet ¼" Stainless Steel Cable O(8) ¼" Cable Clamps

O(8) 834 Aluminum Chock Brackets O(4) Thimbles

O(2) 12' Aluminum Bunks with Rubber Pads O(2) 6" x 9' Aluminum Cradle Beams

O(2) 6" x 12'6" Aluminum Overhead Beams

4000# Capacity

Sling Kit Parts List:

O(1) AMS 4000 (Motor/Gearplate/Switch/GFI) O(4) Thimbles

O(4) 102G Strap Bearings O(4) ½" x 1½" Bolts/Nuts/Locks/Flats

O(4) 560 Aluminum Pulleys O(8) 1/4" Cable Clamps

O(80) Feet 1/4" Stainless Steel Cable O(2) 4" x 14' Nylon Slings

O(2) 6" x 12'6" Aluminum Overhead Beams

Cradle Kit Parts List:

O(1) AMS 4000 (Motor/Gearplate/Switch/GFI) O(4) $\frac{1}{2}$ " x $\frac{1}{2}$ " Bolts/Nuts/Locks/Flats O(4) 102G Strap Bearings O(8) $\frac{1}{2}$ " x 6" Bolts/Nuts/Locks/Flats

O(4) 560 Aluminum Pulleys O(8) ½" x 3" Bolts/Nuts/Locks/Flats

O(80) Feet ¼" Stainless Steel Cable O(8) ¼" Cable Clamps

O(8) 834 Aluminum Chock Brackets O(4) Thimbles

O(2) 12' Aluminum Bunks with Rubber Pads O(2) 6" x 9' Aluminum Cradle Beams

O(2) 6" x 12'6" Aluminum Overhead Beams

6000# Capacity

Sling Kit Parts List:

O(1) AMS 3000 (Motor/Gearplate/Switch/GFI) O(4) Thimbles

O(4) 102G Strap Bearings O(4) ½" x 1½" Bolts/Nuts/Locks/Flats

O(8) 560 Aluminum Pulleys O(8) ¼" Cable Clamps

O(120) Feet 1/4" Stainless Steel Cable O(2) 4" x 14' Nylon Slings

O(2) 6" x 12'6" Aluminum Overhead Beams

Cradle Kit Parts List:

O(1) AMS 3000 (Motor/Gearplate/Switch/GFI) O(4) $\frac{1}{2}$ " x $\frac{1}{2}$ " Bolts/Nuts/Locks/Flats O(4) 102G Strap Bearings O(8) $\frac{1}{2}$ " x 6" Bolts/Nuts/Locks/Flats

O(8) 560 Aluminum Pulleys
O(8) ½" x 3" Bolts/Nuts/Locks/Flats

O(140) Feet ¼" Stainless Steel Cable O(8) ¼" Cable Clamps

O(8) 834 Aluminum Chock Brackets O(4) Thimbles

O(2) 12' Aluminum Bunks with Rubber Pads O(2) 6" x 9' Aluminum Cradle Beams

O(2) 6" x 12'6" Aluminum Overhead Beams

Additional Parts Required

O(1) 2" Schedule 40 Galvanized Pipe (21')

Optional Parts for Boat Lifts Available:

■Weighted Slings

(For Sling Kit Only)

■Cable Weights

(For Sling Kit Only)

■6", 8", and 10" Slings

(For Sling Kit Only)

■Remotes

■White Gearbox Cover

> CHECK BOXES FOR ALL PARTS BEFORE FREIGHT COMPANY LEAVES!

>THIS KIT IS A BOAT LIFT AND IS INTENDED TO BE USED AS ONLY A BOAT LIFT.

DO NOT USE THIS LIFT TO PICK UP HUMANS.

>DO NOT WORK UNDER A HANGING BOAT!

>ALL ELECTRICAL MODIFICATIONS MUST BE DONE BY A CERTIFIED ELECTRICIAN!

Tools Required for Installation:

■Electric Drill

■1/2" Wood Bits

■1/2" Steel Bits

■5/16" Steel Bits

Screw Drivers

Hammer

Wrenches

Level

■Rope

■Pencil

TROUBLESHOOTING:

Lift will Not Pick up Boat

- 1)Boat weighs more than lift capacity
- 2)Low voltage
- 3)Belt slipping
- 4)Gearplate or pipe binding due to improper alignment

Lift Making Excessive Noise


- 1)Needs to be greased
- 2)Pipe or gearbox out of aligment
- 3)Cable rubbing against 102 assemblies

Cable Backlashing

- 1)Add cable weights to pulleys
- 2)Upgrade to weighted slings.
- 3) Cables rubbing against 102 assemblies

FOLLOW THESE STEPS IN ORDER TO SAVE TIME

CONNECTTHE 102G STRAP BEARINGTO THE OVERHEAD ALUMINUM BEAM USING
THE SUPPLIED 1/2 X 1 1/2 BOLTS/NUTS/LOCKS/WASHERS.
SETTHE OVERHEAD ALUMINUM BEAMS INTO PLACE 10' APART OVER THE LIFT
POINTS.
SLIDETHE PIPE INTO THE STRAP BEARINGS.
THE PIPE SHOULD BE RUNNING PARALLEL WITH THE BOAT, DOWN THE CENTER.
MOUNTTHE 560TO THE TAB ON THE OVERHEAD ALUMINUM BEAM ACROSS FROM
THE 102G.
DRILL A 5/16" HOLETHROUGHTHE PIPE IN THE CENTER OF EACH OF THE 102
ASSEMBLIES.
□INSTALLTHE MOTOR ON THE GEARPLATE AND TIGHTEN THE BELT.
□ HANGTHE GEARBOX ON THE PIPE AND BOLTTO THE GEARBOX MOUNT.
☐MARK A HOLE ON THE GEARPLATE AND DRILL A ½"HOLE THROUGH THE PIPE AND
BOLT UP.
SKIP TO 11 IF INSTALLING A 6000# KIT.
RUNTHE CABLETHROUGHTHE PIPE AND OVER TO THE PULLEY ATTACHING LOOSE
ENDSTOTHE SLINGS, OR CRADLE BEAM WITH THE PROVIDED CLAMPS. GO TO 15.
□RUNTHE CABLETHROUGHTHE PIPE OVER TO THE TOP 560 PULLEY, DOWN TO THE
BOTTOM 560 PULLEY, AND DEADMAN OFF ON THE OVERHEAD BEAM.
☐ ATTACHTHE PULLEYTO THE SLING, OR CRADLE BY REMOVING THE BOLT ON THE
PULLEY.
☐YOU CAN LEVELTHE SLING, OR CRADLE BEAM BY PULLING DOWN ON THE CABLE.
ONCE LEVEL, TURN ONTHE WINCH. ONCE TWO WRAPS ARE MADE ONTO THE PIPE
THE CABLE IS LOCKED INTO POSITION AND WILL NOT MOVE.
☐MAKE SURE THE CABLESWRAP OPPOSING EACH OTHER WITHOUT STACKING
(STACKING CABLESWILL REDUCETHE LIFE OF THE CABLES).
☐GREASETHE GEARBOX ATTHETHREE ZERTS AND SPREAD A LIBERAL AMOUNT OF
GREASE ON THE FLYWHEEL.
IF YOU ARE INSTALLING A SLING KIT YOU ARE FINISHED.
□ ASSEMBLETHE CHOCK BRACKETS AS SHOWN IN THE DIAGRAM AND CONNECT TO
THE CRADLE BEAM. THE BUNK BOARDS SHOULD BE ANGLED TO CONFORM TO THE
BOTTOM OF THE BOAT (ON AN 8 1/2' BOAT THE AFT CHOCK BRACKETS SHOULD BE
ABOUT 60" APART AND THE FORWARD CHOCK BRACKETS SHOULD BE ABOUT 56"
APART; ON FLAT BOTTOM BOATS STAND THE BOARDS SO THAT THEY ARE 90 DEGREES
TO THE BUNK BOARDS.
☐IFYOU PURCHASED THE OPTIONAL CABLE GUIDE POSTS CONNECT BETWEEN THE
CRADLE AND THE 560 PULLEYS.




FOR OPTIMUM PERFORMANCE :

EQUAL WEIGHT DISTRIBUTION IS REQUIRED ON ALL 4 CABLES.

4-POINT SLING HOIST

TO OBTAIN EQUAL WEIGHT DISTRIBUTION:

I. USE BALANCE POINT OF BOAT. 2.00 NOT. USE CENTER OF BOAT LENGTH. INSTRUCTIONS FOR WEIGHT DISTRIBUTION SCALE NONE NO. I-502



FOR OPTIMUM PERFORMANCE :

EQUAL WEIGHT DISTRIBUTION IS REQUIRED ON ALL 4 CABLES.

4-POINT CRADLE HOIST

TO OBTAIN EQUAL WEIGHT DISTRIBUTION:

I USE BALANCE POINT OF BOAT.

2.DO NOT USE CENTER OF BOAT LENGTH


INSTRUCTIONS FOR WEIGHT DISTRIBUTION

SCALE NONE

NO. I-503

560S PULLEYS LUNMAR BOAT LIFTS 337-430-0533 6000 CRADLE KIT 2) WITH A HAMMER DRIVE BUSHING HALF WAY INTO PAD EYE BY STRIKING BOLT HEAD AS SHOWN RIGHT PRESSED INTO 7/8 HOPES ON PAD EYES OF CRADLE BEAMS. INTO OILITE BUSHING AS SHOWN LEFT 1) INSERT BOLT/WASHER REMOVE BOLT AND OILITE BUSHING TO ATTACH TO SLING OR CRADLE BUSHING MUST BE 560S PULLEY OILITE BUSHING

INBOARD SKI LUNMAR 3000, 4000, & 6000 CL BEAM LAYOUT FOR COMPETITION BOATS WITH CENTER ENGINES



LUNMAR BOAT LIFTS 3715 HWY 27 SOUTH SULPHUR LA 70665 337-558-7200 337-558-7202 (FAX)

