


Operating instructions

Tensile Tester Accura Dat

Serial:	Typenschild klein
----------------	-------------------



MUNSCH Kunststoff-Schweißtechnik GmbH

Im Staudchen • D-56235 Ransbach-Baumbach

Tel.: +49 (0) 2623 898-80

Fax: +49 (0) 2623 898-85

E-Mail: info-kst@munsch.de

<http://www.munschwelding.com>

Firmensitz/Registered Office: Im Staudchen, D-56235 Ransbach-Baumbach

Registergericht/Registration Court: Amtsgericht Montabaur, HRB 3959

Geschäftsführer/Managing Director: Stefan Munsch

Introduction

The tensile tester, developed and manufactured by MUNSCH Kunststoff-Schweißtechnik GmbH, is a machine with an own actuator, which tests welding samples by tension (thermoplastic welded samples). The tensile tester is developed for outdoor use, but may also be used indoor.

ATTENTION

This machine is an electromechanical Unit with moving parts, which are driven my high force. It is necessary to be careful in using the machine, especially with the moving parts (no contact with clothes, hair or body parts).

Crushing hazard!!!

Content

Technical Data	3
Safety	3
Product description	5
Preparation of the unit	6
Menu guide	7
Configuration	8
Show data	12
Backup and test protocol	13
Deleting data	20
Transport / Storage	21
Service and Repair	21
EC-Declaration of Conformity by the Manufacturer	22

Note: These operating instructions must always be available to the machine operators.
 Make sure to read them carefully before placing the unit in service.
Very important!

Technical Data

Voltage	V~	100, 120, 230
Power consumption	W	200
Max. Force	N	4000
Temperature range of use	°C	-5 bis +80
Tolerance	%	<3% FS at 20°C
Min. carrier distance	mm	5
Max. carrier distance	mm	300
Prüfgeschwindigkeit	mm/min.	10 – 300
Max. sheet thickness	mm	7
Max. sheet width	mm	40 (60 optional)
SD-Slot		Ja
Loudness	L _{pA} (dB)	<70
Weight	kg	38
Dimensions (L x W x H)	mm	1270 x 260 x 270
Conformity marks		CE
Safety marks		
Protection class		

Safety

	<p>Lebensgefahr beim Öffnen des Gerätes, da spannungsführende Komponenten und Anschlüsse freigelegt werden. Vor dem Öffnen des Gerätes muss dieses <u>allpolig</u> vom Netz getrennt werden. Ein beschädigtes Anschlusskabel kann zu einem lebensgefährlichen elektrischen Schlag führen! Nennspannung, die auf dem Typenschild des Gerätes angegeben ist, muss mit der Netzspannung übereinstimmen. Gegebenenfalls Elektrizitäts-Versorgungs-Unternehmen konsultieren.</p>
	<p>Geräte der Schutzklasse I Gerät nur an Steckdosen mit Schutzleiter anschließen; jede Unterbrechung des Schutzleiters ist gefährlich! Nur Verlängerungskabel mit ausreichendem Kabelquerschnitt und Schutzleiter verwenden!</p>
<p>FI</p>	<p>FI-Schalter ist für den Personenschutz erforderlich!</p>
	<p>Gerät muss beobachtet betrieben werden.</p>
	<p>Gerät vor eindringender Feuchtigkeit und Nässe schützen!</p>
	<p>Während der Betriebsphase dürfen Antriebsspindel und Schlitten nicht berührt werden!</p>
	<p>Schlitten darf bei eingespannter Probe nicht eingefahren werden.</p>

Product description




fig. 1

- 1 - Controller housing
- 2 - On-/Off-Switch, Main fuse
- 3 - Display
- 4 - SD-Slot
- 5 - Control panel
- 6 - Probe carriers




fig. 2

Preparation of the unit

A special preparation or configuration of the working unit is not absolutely necessary. Only the testing speed has to be adjusted.

When operating the unit with power supply from a generator set, make sure that the generating capacity is sufficient.

Menu guide

Activating the machine, the main menu appears on the display (fig. 4).





fig. 4

Menu items

Designation	Description
Position	In this menu you can move the slide left and right manually.
Measure	In this menu you can test the welding sample
Measure+Autoposition	In this menu you can test the welding sample. The machine sets its own start point.
Show Data	In this menu you can have a look at all measured tests.
Save Data	In this menu you can save the tests to a flash memory.
Delete Data	Saved by Code. Only for qualified personal.
Configuration	Saved by Code. Only for qualified personal.

Tastenbelegung

Taste	Menü/Eingabe	Name	Beschreibung
	Menu	Up	Wandering upwards in the menu
	Value setting		Upscaling of a value
	Movement	Left	Moving the slide to the left
	Menu	Down	Wandering downwards in the menu
	Value setting		Downscaling of a value
	Movement	Right	Moving the slide to the right
	Menu	Back	Jumping back to the previous menu
	Value setting		Cancel value setting
	Menu	OK	Confirming the choice
	Value setting		Jumping forward in the line

Configuration

Please select the menu item “Configuration” from the main menu (fig. 4) and confirm with “OK”. Now you will be asked for a password.

Please change the password from “0000” to “8980” by pushing the “up” and “down” buttons and carry on to the next digit by confirming with “OK”. You will not see any numbers but only stars. The numbers of each adjustable digit are sorted like the locker of a briefcase.




fig. 5

Proceed as follows:

Old number	0		0		0		0	
Instruction	2x „Down“	OK	1x „Down“	OK	2x „Down“	OK	-	OK
New number	8		9		8		0	




fig. 6

Now the configuration menu appears where you can change the display contrast, the unit of temperature and the language of menu.

If you are working at low outdoor temperatures, it could be reasonable to higher the display contrast and if you are working at high outdoor temperatures, it should be lowered.

To change a value please select it and confirm with “OK”. After having changed it please confirm again with “OK”.

Return to the main menu by pressing “Back”.

Menu „Position“



Select the menu item „Position“ in the main menu (fig. 4) with the cursor and the up-/down- buttons and confirm your choice with the “OK”-button.

The menu „Position“ appears.

Move the slide to the designated position by pushing the right and left buttons. Moving distance is limited by triggers.

Now install your sample and move the slide to the designated starting position.

Return to the main menu by pushing the Back-Button.

fig. 7

ATTENTION!!!

By pushing the emergency button, the machine stops and returns immediately to the main menu. It does not restart automatically!!!

You have to unlock the button to be able to restart again.

Menu „Measure+Autoposition“

Select the item „Measure+Autoposition“ from the main menu and confirm with „OK“.

The menu „Measure+Autoposition“ appears.



fig. 8

Now a number of values appears.

You can change them as follows:

Select the value with the Up- and Down-Buttons and confirm with OK.

Change the value by using the Up- and Down-Buttons and confirm afterwards with OK. ¹⁾

Name, Nr., Date and Time

Value	Description
Speed	Here you can change the testing speed
Force	Here you can correct the shown force
Name	Here you can enter the name of the construction site or of the worker. By pressing "Up"/"Down" you can set the letter or digit. ¹⁾ With "OK" you go one sign forward.
Nr.	Here, all of the welding joints are numbered. At every start of the machine, it increases the number (beginning at "1").
Date	Here you can see/set the actual date.
Time	Here you can see/set the actual time.

If all inputs are confirmed, change to the item "Start action", and confirm with "OK".

1) The characters are sorted as follows: a;...;z;A;...;Z;0;...;9;_

Auto positioning starts after confirmation.



fig. 9

After the Positioning the machine asks for confirmation to start the measurement.




fig. 10

Measurement starts after confirmation.




fig. 11

The machine constantly checks the speed and adjusts it.
The machine records pressure and distance. Distance is calculated by time and actual speed.
If the welding sample breaks (decrease of measured pressure below 50N), the measurement automatically stops and the tensile tester goes back to start position.
Measurement can be stopped manually by pushing the Back-Button.
By confirming with OK afterwards, the tensile tester drives back to the start position.
Pressure is shown with a tolerance of 5N and is only used to make out the distance where the welding sample goes defective.

The machine automatically drives back with high speed to the start position.

ATTENTION!!!

By pushing the emergency button, the machine stops and returns immediately to the main menu. It does not restart automatically!!! There is no chance to proceed with the actual measurement!!! You have to unlock the button to be able to restart.

Show data

Please select „Show Data“ from the main menu and confirm with OK.

Name	Date	Time
Probe		
03	11.03.	09:28
04	11.03.	10:00
05	11.03.	11:11

Please select the preferred test and confirm with OK.


fig. 12

Probe Data	
Name:	Probe
Number:	03
Date:	11.03.14
Time:	09:28
Dist.:	5.98 mm
Speed.:	50 mm/min
Force:	475 N
RecDif:	20 [ms]

Now appears the result menu of the measurement with all of its data. The shown pressure is the maximum measured pressure and the shown distance is the complete distance the machine passed during the test.

Please confirm with OK to see the power-off chart (fig. 14).

fig. 13



Please confirm with OK to get to the table of values. To scroll through the data please use the up and down buttons. Therewith you can find out the exact point of failure on the machine.

fig. 14

Way[mm]	Force [N]
0.00	0
0.00	0
0.00	2
0.00	2
0.03	2
0.03	5
0.05	6
0.07	8
0.09	10

Return to the main menu by using the Back button.

fig. 15

Backup and test protocol

Technical information

Backup-medium	Internal memory
Backup-medium for data backup	SD-flash memory
Maximum capacity of the SD-card	2 GB
Supported manufacturers	DeLOCK
Formatting	FAT 32
Maximum data-amount (at 5cm interval)	2500 Measurements
File format	.txt

To be able to evaluate the measured data, you need Microsoft Office Excel 2003 or higher version.

Backup of measured data

Please insert the supplied SD-flash memory card as shown on the machine with power contacts to the top into the card reader, until it locks in.

Now choose in the main menu the item “Save Data”.




fig.16

After the data backup you may remove the SD-flash memory card by pressing on it again. Finally you may save the data on your PC or notebook.

Now you can convert, save and print the data with the on the flash memory card supplied evaluation software.

Please look to the following chapter “Creating a test protocol”.

Creating a test protocol

After copying the data from the SD-flash memory card to the PC, you may look at it.
The measurements are structured as follows:

The single values are separated by commas (,).




fig. 17

Creating the test protocol

1. Open the delivered evaluation software.
2. Click on „Deutsch“, then on the menu arrow, then on „English“ and then on „Sprache“, to change the language.



fig. 18

3. Click on (...) to select a record file.



Abb. 19

4. Select the file and click on „Öpen“




fig. 20

- Select the construction site / data line. Therefore open the dropdown menu and select the designated line.



fig. 21

- A list of all at this building site recorded welding joints appears. By setting or deleting of an “x” in the last column, single joints can be selected for the protocol.



fig. 22

- Please fill in the blue highlighted gaps and save the protocol by a click on “Create test report”.



fig. 23

- In the footer appears a number of tabs.



fig. 24

Test report: A protocol gets created with the inserted data and the sheet number in its head. After that exists the possibility to fill in the environmental conditions and the conditions of the welding. After that follow the set values and measured values for maximum 4 welding samples. The blue areas at the bottom may be used for comments and signatures. If you tested more than 4 joints, the software creates for every 4 joints a new sheet of test protocol.

Test report				No.	1				
Construction Project	MUNSCH 1								
Constructing company	Exemplary company	Manufacturer	Exemplary Manufacturer						
Welder	Exemplary welder	Nominal Thickness	Sheet thickness						
Welding machine	Wedge It MULTI	Raw material	Exemplary sheet material						
Approval number	01	02	03						
Date	28.02.14	28.02.14	28.02.14						
Time	09:51	10:02	10:07						
Weather conditions									
General (cloudage, wind)									
Air temperature in °C									
Relative humidity in %									
Sheet condition									
Surface									
Joining area									
Surface temperature in °C									
Welding parameters									
	Max.	End	Max.	End	Max.	End	Max.	End	
Distance in mm	IST	15,51	20,61	6,62	7,99	1,88	1,88		
Pressure in N	IST	435	290	325	97	0	0		
Speed in mm/min	IST	25		25		25			
Sample									
Test	No.								
Removal of the sample	No.								
Annotation / Comment									
Welder		Site engineer (principal)		External controller					
Date	Signature	Date	Signature	Date	Signature				

fig. 25

Attach. Slide: In this window you can see, specifically for every joint, the graphical evaluation. Mentioned are the trends of temperature, speed and pressure. Above these graphs, you'll find the head data of the test protocol, the test number, and the start time of the test. Below the graphs, you'll see the maximums and minimums of the graphs.




fig. 26

Optional:

- Click on „Save“, to backup the test protocol and the graphs and tables to a secured file. You prevent an overwriting of your evaluated data.



fig. 28

This file now can be saved on the hard drive of your computer.

- By clicking on „Reset“, you empty the window. Now you may load and evaluate a new test file.



fig. 29

Deleting data




fig. 30


Please select "Delete Data" from the main menu and confirm with "OK".
Now you will be asked if you really want to delete.
Please confirm deletion with "OK".

Transport / Storage

The machine may only be stored or transported in the delivered box.
 The machine may be used in its box and therefore is usable on construction sites.


Service and Repair

Repairs shall be carried out exclusively by MUNSCH Kunststoff-Schweißtechnik GmbH. Any warranties for units which are no longer in the original condition shall be expressly excluded. The units may not be modified and/or changed in any way whatsoever. Any liability for damage resulting from improper use or normal wear and tear of the units shall be excluded.
 Please include always this sheet when sending in the machine for repair or calibration.



Date	Operating hours	Type of repair	Carried out by:

EG-Konformitätserklärung des Herstellers
nach der EG-Maschinenrichtlinie 2006/42/EG Anhang II, Nr. 1 A



EC-Declaration of Conformity by the Manufacturer
as defined by machinery directive 2006/42/EC, Annex II, No. 1 A

MUNSCH Kunststoff-Schweißtechnik GmbH
Im Staudchen
D-56235 Ransbach-Baumbach
Deutschland

Mr. Johann Dausenau,
Kunststoffschweißtechnik GmbH,
is authorised to compile the technical documentation.

We hereby declare that the Tensile tester

Machine type: Tensile tester
Type designation: Accura-Dat

is in accordance with all relevant provisions of the EC Machinery Directive.

The following harmonised standards (or parts of these standards) were applied:

- | | |
|--|--------------------------|
| <input checked="" type="checkbox"/> DIN EN ISO 12100: 2010 | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> |

Die Biegeprüfvorrichtungen sind auch in Übereinstimmung mit folgenden EG-Richtlinien:

- | | |
|---|---|
| <input checked="" type="checkbox"/> EU Low-Voltage Directive 2014/35/EU | <input checked="" type="checkbox"/> EU EMC Directive 2014/30/EU |
| <input checked="" type="checkbox"/> EN 60204-1 (VDE 0113 Part 1): 2011 | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> VDE 0701 Teil 1: 2008 | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> |

This industrial tool complies with the aforesaid standards insofar as it is used at the contractually agreed conditions. The operator is responsible for this.

In the event of any modifications to the machine/unit or use not as intended, this declaration becomes invalid unless the manufacturer's prior written approval has expressly been given.

Ransbach-Baumbach, 10.02.2015

Dipl.-Ing. Stefan Munsch
Geschäftsführer