Installation instructions

1/2 inch Water pipes lines: A9622F4C1 ,A9622F4B1, A9622F4R1, A9622F4BG1

(1) Water leak reasons and solution for shower head

The O rings damaged inside the extensions: need replace new O rings

The extensions do not tighten well and correctly: re-tighten the extensions

The valve body installed too deeply: re-install the valve body or customize longer extensions

The adapter of head valve body don't tighten well: re-tighten it. Be sure not un-tighten the adapters during connect water pipes to the adapters.


All shower head are made of stainless and brass and they are not easy to be damaged and they won't leak water.


If you find any water leak issue, pls contact us and we will supply free parts such as O rings and longer extensions.


Pls install the items strictly and do not uninstall each part from the original item.


The detail installation instruction are below


Shower head installation steps:

















As shown in the figure, install the control valve, and fix the thermostatic control valve with the screws that originally removed the flap. After fixing the control valve, open the water pipe switch. Please pay attention to check whether there is any leakage between the control valve and the base. Control the valve and check whether the 6 rubber rings under the control valve are installed correctly. After the inspection, please reinstall the control valve. Then test whether the diverter spool is normal. The next step is to test whether the water temperature is 38 $^\circ~\pm$ 1 under normal use. If there is high or low temperature, please check if the red pen mark on the thermostat spool is aligned. If the temperature is not constant, please check whether the hot and cold water pipes and the hot and cold water inlets of the main body are installed correctly. After testing all functions, please install the panel and the switch handle. Make sure that the direction of the handle bar is facing the 38 ° position.