# TENMARS Multi IAQ Monitor

TM-380 User's Manual





#### **Contents:**

1	Applica	tion	1
2	Access	ories	1
3	Safety I	Precaution	1
4	Instrum	ent Description	2
	4.1	Feature and function	2
	4.2	Indication on the LCD display	3
5	Operati	on	4
	5.1	Power on/off	5
	5.2	Auto Power Off	5
	5.3	Backlight mode	5
	5.4	MAX/MIN,AVG and MAN MIN	5
	5.5	REC Manual record	5
	5.6	LOG starts the auto-recording function	6
	5.7	Read the data recorded in the memory.	
	5.8	°C or °F units	
	5.9	Clear memory	6
	5.10	•1)) Turn on / off the key sound	7
	5.11	Resume the factory settings	7
	5.12	Function settings	7
6		Specifications1	
7	Genera	Specifications1	4
	7.1	PM2.51	4
	7.2	PM101	4
	7.3	CO <sub>2</sub> 1	4
	7.4	Temperature 1	5
	7.5	Humidity 1	
8	Mainter	nance or Repair1	
		t disposal 1	

#### 1 Application

This air quality meter can measure and display CO2, PM2.5, Humidity and Temperature measurements and is ideal for monitoring indoor air quality in a variety of environments.

#### 2 Accessories

- Meter (with a 3.7V Rechargeable lithium battery)
- 1 User's Manual
- Micro USB cable

#### 3 Safety Precaution



Caution! Please refer to this manual. Improper use may damage the meter and its components.




Complies with European Directive.

- Do not operate in environments with flammable gas or humid environments.
- Operating altitude: up to 2000M.
- Operating environment: Indoor use; Pollution degree 2.
- Clean with soft cloth when dirty, such as glasses cloth. Do not clean with chemicals and other solvents.
- EMC: EN61326-1:CISPR 11:Group 1, Class B
- Class B Equipment for use in all establishments other than domestic.
- Group 1 RF energy generated is needed for internal functioning.


#### 4 Instrument Description

#### 4.1 Feature and function



- 1. LCD
- 2. Right-side button
- 3. Memory reading / Up button
- 4. MAX / MIN / AVG button
- 5. Power button
- Single log and auto-record button/Down button
- 7. Temperature and humidity sensing port
- 8. Air outlet for sensor
- 9. Air inlet for sensor
- 10. Micro USB jack

#### 4.2 Indication on the LCD display



1.MAX / MIN /AVG

/MAN MIN

- 2.Manual recording
- 3. Auto-recording


4.Read record


- 5.Battery indicator
- 6. Auto-power off
- 7.Buzzer
- 8.Alarm

- 9.CO<sub>2</sub>
- 10.PM2.5
- 11. Temperature
- 12.MM minute,
  - SS second
- 13.PM10
- 14. Humidity

#### 5 Operation

Please hold the meter in the following way for the correct measured value:





#### 5.1 Power on/off

Press to turn the power on or off.

#### 5.2 Auto Power Off

At the power-on status, press and hold of for more than 2 seconds to disable or resume auto power off function. When auto power off is activated, the indicator appearing, and it will automatically turn off after 30 minutes.

#### 5.3 Backlight mode

Press "right-side button" to turn on or off the backlight. (When the red backlight for alarm is on, this button is invalid)
The backlight mode is turned off automatically after 15 seconds.

## 5.4 MAX/MIN AVG and MAN MIN

Press MAX to enter this function, the MAX is shown on the screen and it displays the maximum value.

Press MAX repeatedly to select the function of MIN/AVG/MAX MIN/MAX and update the displayed value. When select MAX MIN function, it displays the current measured value.

## 5.5 **REC Manual record**

Press to save one data log, the "REC" and the log number appear on the LCD for one second. For an example of the log number 10, it will increase by 1 when pressing

every time. When reaching the maximum log number 20. Full appears.

## 5.6 LOG starts the auto-recording function

Press and hold for more than 2 seconds, "LOG" appears on the LCD, and auto-recording starts. If the power is insufficient during auto-recording, appearing, auto-recording will be forcibly stopped. When reaching the maximum log number 20, Fill appears.

Press and hold again for more than 2 seconds to exit the auto-recording function.

## 5.7 Read the data recorded in the memory

Press to enter the memory-reading mode, while R-M and the log number appear on the LCD for one second, the record is then displayed. Read the data recorded in the memory with or ...

Press and hold to exit this mode.

#### 5.8 °C or °F units

At the shutdown status, press and hold , then press to turn on the meter, after the software version appears, release

Repeat the above steps to switch the unit.

#### 5.9 Clear memory

At the shutdown status, press and hold  $\begin{tabular}{l} MAX \\ MN \end{tabular}$  and then press

to turn on the meter, the **LLr** and software version appears successively on the LCD, release the to clear the memory.

## 5.10 •)) Turn on / off the key sound

The sound is defaulted as on and the •1) is displayed.

At the shutdown status, press and hold then press to turn on the meter, after the software version appears, release and the •1) disappears, the key sound is off.

Repeat the above step to tun on the key sound.

#### 5.11 Resume the factory settings

At the shutdown status, press and hold "right-side button" and then press ①, the **FLLr** and software version appears successively on the LCD, release the "right-side button" to complete the process of resuming to the factory settings and clearing the memory.

- > Auto-shutdown: OFF
- > Key sound: On
- The calibration value resumed to 0.
- ➤ CO₂ Abc OFF
- Memory cleared

#### 5.12 Function settings

Press "right-side button" for more than 2 seconds to enter the setting mode.

Press the "right-side button" repeatedly to enter the setting function 1 ~ 8 in sequence:

#### SET 1. Time interval setting

1. The LCD displays:



- 2. Press or to select the interval 5 seconds / 10 seconds / 5 minutes / 10 minutes / 20 minutes / 30 minutes / 60 minutes; the default value is 5 seconds.
- 3. Press the "right-side button" again to enter set 2.

#### SET 2. CO<sub>2</sub> alarm setting

The LCD displays:



- 2. Press MAN to move the digit, and the selected digit will flash.
- 3. Press or lo increase or decrease the CO<sub>2</sub> value.
- 4. Press the "right-side button" again to enter set 3.

#### SET 3. PM2.5 alarm setting

The LCD displays:



- 2. Press MAX to move the digit, and the selected digit will flash.
- 3. Press or to increase or decrease the CO<sub>2</sub> value.
- 4. Press the "right-side button" again to enter **set 4**.

#### SET 4. PM10 alarm setting

The LCD displays:



- 2. Press MAN to move the digit, and the selected digit will flash. \_\_\_
- 3. Press or to increase or decrease the CO<sub>2</sub> value.
- 4. Press the "right-side button" again to enter set 5.

#### SET 5. (Factory use only) CO<sub>2</sub> Abc self-calibration mode

1. The LCD displays:



- This is for factory calibration use only. Please do not change it.
- 3. Click the "right-side button" again to enter set 6.

#### SET 6. CO<sub>2</sub> manual calibration

1. The LCD displays:



- Directly increase or decrease the displayed value of CO<sub>2</sub>, press the MAX to move the digit, and the selected digit will flash.
- 3. Press or to modify the value.
- 4. Press the "right-side button" again to enter **set 7**.

#### SET 7. Temperature calibration

The LCD displays:



- Directly increase or decrease the temperature value, press the MAX to move the digit, and the selected digit will flash.
- 3. Press or to modify the value.
- 4. Press the "right-side button" again to enter set 8.

#### **SET 8. Humidity calibration**

1. The LCD displays:



- Directly increase or decrease the temperature value, press the MAX to move the digit, and the selected digit will flash.
- 3. Press or to modify the value.
- Press the right-side button again to return to the measurement mode.

#### 6 General Specifications

- Real-time measurement of CO<sub>2</sub>/PM2.5/PM10/temperature/humidity.
- Maximum / minimum / average value.
- Auto-power on / off function.
- Adjustment and calibration function (CO2/temperature/humidity).
- CO2/PM2.5/PM10 red backlight alarm.
- Manual record and auto-record.
- Key sound assists to ensure the operation works.
- Overload indication \$\overline{U}\$.
- Battery: 3.7V 2000mAh rechargeable lithium battery
- Transformer for charging: 1A/5V
- Battery life: continuous use for approximately 6 hours
- 5V micro USB interface for external power supply
- When battery-low indicator shows as the following figure, the power will be turned off after 5 seconds.



- Charging indication: The battery indicator will sequentially vary as 

  → 

  from right to left during charging and keep 

  when fully charged.
- °C or °F unit selection.
- When the external power supply is connected, the auto-power off is disabled, and the white backlight is always on.

■ CO<sub>2</sub> /PM2.5/PM10 red backlight alarm setting function

Setting	CO2	PM2.5	PM10
value	1000PPM	35µg/m³	75µg/m³

When the measured value reaches the setting value for alarm, the LCD backlight shines in red and related measurement items flash.

- 20 logs for manual and automatic recording values.
- Auto-recording time interval setting: 5 seconds, 10 seconds, 5 minutes, 10 minutes, 20 minutes, 30 minutes, 60 minutes.
- Sampling time: 2.5 seconds (5 types, 0.5 seconds for each).
- Dimensions: 150x65x22mm (L x W x H).
- Weight: 190 g.
- Operating temperature and humidity: 0°C ~ +50°C, <80%RH (no condensation).</li>
- Storage temperature and humidity: 0°C ~ +60°C,
   <70%RH (no condensation).</li>
- Display size: 52mm (L) x 40mm (W).



#### Caution

If to use the meter in a high-humidity environment, please place the meter in a low-humidity environment for 24 hours after use.

7 General Specifications
Ambient temperature range for accurate measure: 18°C (64°F) ~ 28°C (82°F)

#### 7.1 PM2.5

Sensor	Laser particulate matter sensor
Measuring range	0-500 μg/m³
Accuracy	±8µg :<=50µg/m³ ±10% of reading value:>50µg/m³
Resolution	1
Reaction time	<10seconds

#### 7.2 PM10

Sensor	Laser particulate matter sensor
Measuring range	0-500 μg/m³
Accuracy	±10µg :<=50µg/m³ ±15% of reading value:>50µg/m³
Resolution	1
Reaction time	<10 seconds

#### 7.3 CO<sub>2</sub>

Sensor	Non-Dispersion Infrared(NDIR)
Measuring	400 to 9999ppm
range	
Accuracy	±70ppm ±3% of readings. (400-2000ppm)
Resolution	±1ppm
Reaction time	90% during about 2 minutes

#### 7.4 Temperature

Sensor	Bandgap temperature sensor
Effective	-10°C~50°C / 14°F~122°F
range	
	±1.0°C/±1.8°F
Accuracy	(Non-charging and 30 minutes after
	charging)
	0.1°C / 0.1F (0~35°C / 32°F~95°F);
Resolution	1°C / 1°F
	(Above 100°C /°F or below -10°C /°F)
Reaction	About 1 second
time	

### 7.5 Humidity

Sensor	Capacitive humidity sensor
Effective	1-99%
range	
	±5.0%RH(10~90%);
Accuracy	±8.0%RH(<10%,>90%) no
-	condensation, at 25°C
Resolution	0.1%
Reaction	About 4 seconds
time	

#### 8 Maintenance or Repair

- For the battery-low indicator: indicates the battery full; indicates the battery low, please charge it in time.
- 2.If dirty, please wipe it with a soft cloth, such as a glasses cloth. Do not wipe it with chemical solvents.
- 3. If fault on the meter, it can only be sent to the authorized service suppliers or sent back to the original factory for maintenance.



#### Caution

When the LCD shows the battery-low indicator , please charge it in time.

#### 9 Product disposal



Caution: This symbol indicates that this product and its accessories shall be subject to a separate collection and correct disposal, please not throw it away directly to avoid environmental pollution.

## **TENMARS**



## Professional Electrical and Environment Test & Measurement Instruments:

LED light meter, Temperature & Humidity meter, Infrared Thermometer, Sound level meter, Light meter, EMF meter, UV Light meter, RF meter, Hot wire Anemometer, Co meter, Anemometer, Lan cable tester, Co2 meter, Solar power meter, Radiation meter, Clamp meter, Multimeter, Phase Rotation test, Digital Insulation tester

Our products of high quality are selling well all over the world

TENMARS ELECTRONICS CO., LTD. 6F, NO.586 Ruiguang Rd, Neihu Dist. Taipei City, Taiwan E-mail: service@tenmars.com http://www.tenmars.com