


USER MANUAL

Coating Thickness Tester



Overview

1. Overview

This instrument adopts a composite probe to measure the thickness of the electroplated coating on the surface of metal materials through a precise sensor without damage. It has the functions of LCD digital display, backlight, maximum and minimum value locking, data reset, data calibration, unit conversion and automatic shutdown, etc. It is an unit that automatically detects the properties of the base material and the thickness of coating through electromagnetic induction and eddy current effect.

This instrument is an essential measuring tool for material surface treatment engineering, and can detect steel, iron, copper, aluminum, alloy, etc and measure the thickness of non-conductive coating (such as paint, oxide film, plastic, ceramic) on metal surface. It's widely used in manufacturing, metal processing, chemical industry, commodity inspection, etc.

Principle of Fe probe magnetic induction:

When the probe is in close contact with the coated magnetic material, the probe and the magnetic material form a closed magnetic circuit, and the thickness of the coating corresponds to the magnetic circuit. The measuring of the coating thickness can be done by detecting the change of magnetic resistance.

Principle of NFe probe eddy current effect:

When the probe is in close contact with the coated nonmagnetic metal material, the probe and the material generate eddy current, and the feedback effect of eddy current on the probe corresponds to the coating thickness. The measuring of the coating thickness can be done by detecting this feedback amount.

Notes

2. Notes

* After receiving the instrument, check and confirm whether it is damaged in transit.

* During detection, it shouldn't be used in the situation where it's the substrate edge, the surface is severely deformed or covered with dust and stains, or the area is too small.

* Non-professional maintenance personnel are forbidden to open the instrument to adjust or repair it.

* If there is dust or other stuff on the probe surface, please wipe it with a clean and wet dust-free cloth. It is forbidden to clean it with solvent or abrasive.


* When the symbol () is displayed on the screen, it means that the battery is insufficient, and should be replaced in time. If it is stored for a long time, please remove the battery to prevent from leakage and corrosion.

* The standard sheet equipped with the instrument is a high-precision accessory, so please keep it properly to prevent the surface from being scratched, deformed or lost. If the surface is covered with dust or stains, please wipe it with a clean dust-free cloth during calibration.

* If the instrument has a large measurement error and abnormal data in use, it should be stopped. First, check whether the battery power is insufficient, turn off the power and restart it. If it fails to return to normal, try to resume the factory settings. If the above methods still fail, please contact the dealer in time.

Name of components

3. Name of components



- ① LCD display
- ② Power/Long press or power on and off, and short press for unit conversion
- ③ MAX/MIN maximum and minimum value locking
- ④ MODE mode conversion key
- ⑤ CAL calibration key, digital adjustment plus
- ⑥ ZERO reset key, digital adjustment minus
- ⑦ Probe
- ⑧ V-groove, used for measuring convex curved surface, such as the surface of steel pipe.
- ⑨ Battery compartment
- ⑩ Lanyard hole
- ⑪ Charging port, indicator LED

Display Description

4. Display Description



| Symbols | Description |
|------------|--|
| SINGLE | Single point measurement mode |
| CONTINUOUS | Fast continuous measurement mode |
| Fe | The base material is Fe, and the magnetic material are steel/iron; |
| NFe | The base material is aluminum, and the nonmagnetic materials are copper/aluminum, etc. |
| ZERO | Reset |
| High | High alarm |
| LOW | Low alarm |
| MAX | Maximum value |
| MIN | Minimum value |
| CAL | Calibration |
| mil | Mil |
| um | Um |
| | Automatic shutdown symbol |
| | Battery under-voltage symbol |
| | Voice broadcast(only for lithium battery voice model) |

Technical parameters

5. Technical parameters


| Type | Battery | lithium battery voice |
|--|---|-----------------------|
| Display | LCD | √ |
| Measuring base | Iron base or aluminum base | √ |
| Sampling method | Iron base: magnetic induction Aluminum base: eddy current effect | √ |
| Measuring range | 0-1500um | √ |
| Resolution | 0.1um | √ |
| Accuracy | Iron base or aluminum base / ± (3%+2um) | √ |
| Automatic shutdown | About 10 minutes | √ |
| Measurement mode | single/continuous | √ |
| Unit | um | um/mil |
| The radius of the minimum convex curvature | 5mm | √ |
| The radius of the minimum concave | 50mm | √ |
| The diameter of the minimum measuring area | 20mm | √ |

How to use

6. How to use

1.Power on and off : Press the () key for a long time to turn on or off the power supply, and the self-test of the instrument will count down for 5 seconds. When starting up, please keep the sensor of the instrument away from any metal object, and from the metal object for at least 5cm

and strong electromagnetic field, otherwise the measurement accuracy cannot be guaranteed and you need to resume the instrument according to the above requirements.




How to use

7. How to use

2.Unit conversion: Press the power key shortly after starting to select the measuring unit of um/mil. (Lithium battery voice model, short press to turn on or turn off voice function)


3.Mode selection: Press the MODE key shortly to select the required measurement mode: SINGLE is the single point measurement mode, and CONTINUOUS is the fast continuous measurement mode.



How to use

8. How to use


5.CONTINUOUS Fast and Continuous measurement mode : Hold the instrument in hand and quickly place the probe vertically on the surface of the material to be measured and lightly press it . The measured value is displayed on the screen. The user can arbitrarily change the measuring point or slide on the surface of the substrate to quickly complete continuous measurement.



How to use

9. How to use


6.Automatic identification of substrate properties: during measurement, the instrument automatically identifies the metal properties of the substrate, and the top of the screen shows that the the base material of Fe is magnetic steel, iron, etc or the base material of NFe is nonmagnetic aluminum, aluminum alloy, copper, etc.



How to use

10. How to use

9.ZERO reset function: Press the MODE key to change the SINGLE single point measurement mode, and the probe will be laid flat on the iron-based or aluminum-based surface. If the value is not ZERO, keep the probe in steady contact with the substrate. Press the ZERO key shortly, and the value displayed on the screen will be zero, and the instrument reset is completed.




How to use

11. How to use

7. Resume the factory settings/User-defined calibration
When the instrument is turned on, press the ZERO key for a long time, and it will beep twice to resume the factory setting. If the high-low alarm function has been set, it is necessary to manually resume the default value.

8. User-defined calibration
The calibration is mainly used for fine-tuning the measurement accuracy of the instrument. When the probe is slightly worn/stored for too long/the temperature and humidity of the environment are harsh/the material to be measured is special, there will be slight deviation of the measured value. At this time, the user needs to simply calibrate the instrument. The operation steps are as follows:

1. Take out the two calibration substrates (the heavy one is iron-based/the light one is aluminum-based) that are attached with the unit, and lay them flat on the desktop, and take out the standard sheet (50um/100um/250um/500um/1000um) attached.
- Notes:
①User calibration mode : 0.0um/50um/100um/250um/500um/1000um, totally 6 calibration points.
②It is strictly forbidden to superimpose the standard sheets for calibration. If the calibration is wrong accidentally, it can be repeated.
③User calibration mode can be multi-point or single-point calibration at one time.
④ Automatic identification of iron base and aluminum base during calibration does not require any conversion.



How to use

12. How to use

2.When the instrument is turned on, long press the CAL key, it beeps once, and the display shows (CAL)CONTINUOUS for the user calibration mode.

3. Zero-point calibration: Place the probe vertically on the iron-based or aluminum-based surface and lightly press it. If the measured value is not zero, hold the unit to keep the probe in steady contact with the substrate. Press the CAL key for a short time, it beeps once and the calibration point 00 flashes. When the screen shows 0.0um, the zero-point calibration is completed. Press the CAL key for a long time to exit the user calibration mode.

4. Place the standard sheet 50um/100um/250um/500um/1000um respectively on the surface of iron base or aluminum base, and the corresponding calibration point should be displayed when the probe contacts. If there is a big error between the display and the placed standard sheet, the method of pressing the CAL key is the same as that of zero calibration.



How to use

13. How to use

9. Replace the battery
① Turn off the power supply of the instrument.
② Use a screwdriver to remove the screw of the battery cover on the back of the instrument.
③ Remove the battery cover and remove the old battery.
④ Replace with a new 1.5V x 2AAA battery.
⑤ Install the battery cover and tighten the fixing screws.

Attachments

11. Attachments

| Name | Quantity |
|--|----------|
| Host | 1 |
| Iron base | 1 |
| Aluminum base | 1 |
| Standard sheet | 5 |
| Instruction manual | 1 |
| Hanging roe | 1 |
| Bag | 1 |
| Alkaline battery 1.5V /AAA | 2 |
| USB Type-C charging cable (only for lithium battery voice model) | 1 |

USER MANUAL

MADE IN CHINA



M101040043