

CERTIFICATION TEST REPORT

515 Gus Hipp Blvd Rockledge, Florida 32955 Telephone (321) 632-2008 http://www.imanna.com Post Office Box 560933 Rockledge, Florida 32956-0933 FAX (321) 690-3360 E-mail: imanna@yourlink.net

CERTIFICATION TEST REPORT 16046-2 MECHANICAL STRENGTH TESTS ON 6-INCH WIDE-LINE SERIES CLEATS #305-6 FOR ACCON MARINE, INC.

CUSTOMER:

ACCON MARINE, INC. 13665 AUTOMOBILE BLVD. CLEARWATER, FL 34622

MANUFACTURER OF TEST ARTICLE: ACCON MARINE, INC. CLEARWATER, FL 34622	REPORT NO.: IMANNA JOB NO.: CUSTOMER P.O. NO.: CONTRACT:	16046-2 16046 N/A N/A
DATE: MARCH 19, 2003 PAGES IN STATE OF FLORIDA <u>ROBERT L. WHITE</u> , being duly swom, deposes and says: The information contained in this report is the result of complete and carefully conducted tests and is to the best of his knowledge true and correct in all respects. <u>Kalut X Minut</u> SUBSCRIBED and swom to before me this 19th day of March , 2003 David H. Hudofma Subscribed and swom to before me this 19th day of March , 2003 David H. Hudofma Subscribed and swom to before me this 19th day of March , 2003 David H. Hudofma Subscribed ADT A A A A A A A A A A A A A A A A A A		3 liability for damages of any kind to person or acial or consequential damages resulting from a service covered by the report. BORATORY, Inc. White NEER

PAGE NO. 2 REPORT NO- 16046-2

1. TEST ARTICLE

Five stainless steel samples of the Wide-Line Series, 6-inch cleats were manufactured and received from Accon Marine in **Clearwater**, Florida.

2. MODEL NUMBER

Wide-Line Series, #305-6

3. <u>REQUIREMENTS</u>

The Requirements for this effort are to perform side pull tests on the received samples.

4. PROCEDURES

Each cleat was mounted to a ³/⁴" thick steel plate in the manner it would be mounted on a boat. The cleats were then subjected to an increasing side load to determine the point of significant bending and/or ultimate load capability (whichever occurs first) in the direction of pull.

5. <u>RESULTS</u>

SAMPLE	MAX LOAD (Ibs)	FAILURE MODE	
1	6,075	RETAINING SCREW HEAD BROKE	
2	7,154	RETAINING SCREW HEAD BROKE	
3	7,369	RETAINING SCREW HEAD BROKE	
4	5,752	RETAINING SCREW HEAD BROKE	
5	6,686	RETAINING SCREW HEAD BROKE	
AVERAGE	6,607		

IMANNA LABORATORY

PAGE NO. 3 REPORT NO. 16046-2



Figure 1. Wide-Line cleat; Typical failure mode (screw head failure).



Figure 2. Wide-Line Cleat; Typical deformity.

6 OBSERVATIONS AND COMMENTS

-

and the

The results presented **herein** apply only to the test article as prepared and as tested. All equipment used in the performance of these tests was calibrated to standards traceable to **the N.I.S.T**.

IMANNA LABORATORY