Troubleshooting for T238 Light sensor

version DTU for Gearbox V2

Fault	Fault Analysis	Solution
No reaction	The connection of motor or	Please use brushed 480 motor and
after	battery is abnormal	battery which the voltage is higher than
connecting the		7.4V, make sure battery and motor is
battery		functional, reconnect motor to make sure
		the circuit is closed then test the DTU
		with battery
Only	1.The connection of motor is	Please confirm motor and gearbox are
pre-loading	abnormal	functional, reconnect motor then test the
function works	2. Fault of motor	DTU with battery
Magazine keeps	For DTU with pre-loading	1.Automatic pre-loading function is
feeding after it	function, circuit for pre-loading	disabled, please return it to retailer for
is attached	function maybe overload	repair
	For DTU without pre-loading	2.For DTU without pre-loading function,
	function, negative of magazine	the negative wire of magazine should be
	could be connected improperly	connected to negative of motor instead
		of negative of battery
Magazine	Fault of magazine	Please reconnect terminals for magazine,
cannot feed	Fault of gearbox	make sure the connection between
gel/BB	Diameter of gel is improper	magazine power supply and DTU is
	Power supply wire of magazine	functional, then do troubleshooting for
	anomaly	magazine/gearbox/ diameter of gel such
		external factors.
Only 2 long	2 long 'beep' means DTU is	Trigger cannot block sensor while
'beep' after	entering programming model. It	released is because that the slot of trigger
battery is	means trigger is pulled while	is too large, or the left surface of trigger is
connected, no	selector plate is at 'auto' position.	too far away from the trigger sensor on
reaction after	If trigger is not pulled, it means	the DTU. Please modify the shape of
the trigger is	the trigger cannot block sensor	trigger then thicken the right surface
pulled	while it is released, DTU detects	5-6mm to reduce the gap, so the trigger
	that trigger is pulled.	can block sensor.
1 long 'beep'	One long 'beep' following by 3	Trigger cannot block sensor while
following by 3	short 'beeps' indicate that DTU is	released is because that the slot of trigger
short 'beeps'	entering 'quick' model, it means	is too large, or the left surface of trigger is
after battery is	trigger is pulled while selector	too far away from the trigger sensor on
connected, no	plate is at 'semi' position. If	the DTU. Please modify the shape of
reaction after	trigger is not pulled, it means	trigger then thicken the right surface
the trigger is	trigger cannot block sensor while	5-6mm to reduce the gap, so the trigger
pulled	it is released, DTU detects that	can block sensor.
	trigger is pulled.	

Only 3 short 'beeps' after battery is connected, no reaction after trigger is pulled	3 short 'beep' means the DTU has Entered shooting mode successfully, it means initialization of DTU is successful. No reaction after the trigger is pulled might be caused by that trigger sensor is blocked by wires or other things or the travel of trigger is not enough to reach the trigger sensor or the trigger sensors on upper and lower circuit boards are broken.	Please investigate wires of gearbox then clean trigger sensors on both sides of circuit boards; Since travel of trigger might not be enough, it is needed to modify the trigger limit of trigger on gearbox to make the trigger is able to reach the trigger sensor; If it is impossible to observe the surface of trigger is normal or not. Please try to remove the trigger and assemble the upper circuit board and attach the motor then connect battery. If it is 2 long 'beep' or a long 'beep' following by 3 short 'beep', it means trigger sensor is functional. Otherwise, trigger sensor is down.
4 short 'beep'	4 short 'beep' is the warning for low voltage warning, it means battery is out or the setting for battery protection is wrong.	Fully charge battery, then set the first term to 5 before testing with battery
'semi' mode	There is a 'beep' while changing	The effective distance is 0.5-2mm, please
only	mode. If there is no such 'beep', it	make sure the sticker on the selector
	means selector sensor which is at	plate is in between this distance; If white
	'auto' position cannot detect	area is not accurate, it is recommended
	white are on the selector plate.	to attach a new sticker on it, do not
	This means the position of stick	blacken it first. If there is only 'auto'
	on selector plate is not rear	mode, blacken the sticker 2mm once
	enough or the black on the	until the position of 'semi' mode is
	sticker is too much or the	accurate.
	surface of the white sticker is	
	too far away from selector	
	sensor.	
'auto' mode	There is a 'beep' while changing	The effective distance of selector sensor
only	Mode. If there is not, it means	Is 0.5-2mm, please make sure the sticker
	DTU detects white area at 'semi'	on the selector plate is in between this
	position, the black area of	distance; If there is only 'auto' mode
	selector plate is not enough	when the gearbox is assembled in the
		gearbox, please blackening the sticker
		for 2mm once until the position of
	Long (boog) in the stars for so the	selector is precious
Long 'Beep'	Long 'beep' is the alarm for motor	Please clean gear sensors on both sides
after Motor	stall, DTU detect gears are not	of circuit boards, Change the battery to a
rotates	rotating, it could be:	battery with higher discharge rate (Higher
few rounds	1. Motor does not drive gears	than 1100mah 25C). Please check and

Motor heating	 rotating 2. Gear sensor is dity 3. Alignment of upper and lower circuit boards is incorrect 4. Discharge of battery is not enough 5. Gear sensor is down Frequent motor heating is mainly caused by high start and shut current and frequent shut. Active Brake of DTU needs to transfer the kinetic energy to heat energy for brake. It is related to the 	modify bulge inside the gearbox in case it interfere the installation of DTU (Alignment of upper and lower circuit board) then reinstall the DTU and test Set the position of piston to 4 or higher in programming model can reduce or close active brake function to reduce motor heating. In addition, change the motor to high torque and low RPM ones can also reduce motor heating.
	performance of motor; heating of motor is normal phenomenon, and it is unavoidable.	
Battery heating	Critical battery heating is mainly caused by that the torque of motor is not enough for load or load is too large. Normally, it is because gears are too tight or the main spring is too strong; it could also be caused by discharge of battery is not enough or it is at overloading status for a long time	Battery with higher discharge rate and capacity is recommended. In addition, connector for battery, it is recommended to use XT30 or mini-Tamiya connector. Investigate the tightness of gears, the strength of main spring and smoothness of gearbox. Change the motor to a high-torque one can relieve this issue.
Critical wire heating	Critical heating of wire is because torque of motor is not enough for load or the load is too much (Gears are too tight or main spring is too strong); It could also be the discharge rate of battery is not enough or the battery is at overload situation for a long time	Battery with higher discharge rate and capacity is recommended. In addition, for connectors of battery, it is recommended to use XT30 or mini-Tamiya connector. Investigate the tightness of gears, the strength of main spring and smoothness of gearbox. Change the motor to a high-torque one can relieve this issue.
Firing instantly after battery is connected	FET chip has damaged	Please investigate battery connectors and motor connectors are reversal or not. Please check is there a short circuit or damage on wires or circuit boards, Please contact after-sales for solution
DTU burn down instantly after	Battery is connected reversely	Please check the connector of battery is Reversal or not, Please contact after-sales

battery is		for solution
connected		
DTU burn down	Polarities of motor (Gearbox) are	Please check connector of motor is
instantly after	connected reversely	reversal or not, is there a short circuit or
trigger is pulled	Short circuit occurs on the wire	damage in wire, Please contact after sales
	that connects motor	for solution.
Motor keeps	Trigger cannot block trigger	Trigger cannot block sensor while
working after	sensor while it is released, the	released is because that the slot of trigger
trigger was	DTU detects that trigger is not	is too large, or the left surface of trigger is
released	released.	too far away from the trigger sensor on
		the DTU. Please modify the shape of
		trigger then thicken the right surface
		5-6mm to reduce the gap, so the trigger
		can block sensor.