



# INSTALLATION INSTRUCTIONS

MS 0107-12 | 04.13.20



**⚠ WARNING:**

Cancer and Reproductive Harm | [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

**ZT** | zippertubing®

7150 W. Erie St, Chandler, AZ 85226

[sales@zippertubing.com](mailto:sales@zippertubing.com)

[zippertubing.com](http://zippertubing.com)

(855) 289.1874



The information shall not be duplicated, reproduced, or disclosed to parties other than the recipient without written authorization from The Zippertubing® Company. The information shall not be used to create products or processes similar to those designed, developed and marketed by The Zippertubing® Company. Any attempt to utilize this information to create products similar to those of The Zippertubing® Company shall be prosecuted to the fullest extent of the law. © Copyright 2020, The Zippertubing® Company, All Rights Reserved.

## **ABOUT ZIPPERTUBING®**

Since 1957, Zippertubing® has been solving every type of cable bundling, heat-shielding, EMI-shielding, specialized heat shrink and marine fairing component challenge. From under the sea to outer space, we have prototyped, manufactured, and shipped custom-engineered solutions for every type of industry. We specialize in creating unique custom solutions in-house from beginning to end, so you feel confident you will receive the perfect product every time.

No matter the size, shape, standards, or specifications, Zippertubing® will abide by any requirements to create a custom solution. If the project has material restrictions or weight limitations, we will create a solution to fit your unique application needs, rather than make your application fit the product. We will draw up, prototype, and refine to ensure the solution is exceeding your expectations.



## **TABLE OF CONTENTS**

<b>INTRODUCTION</b> .....	3
<b>SIZING CHART</b> .....	3
<b>INSTALLATION</b> .....	4
<b>TROUBLESHOOTING</b> .....	6

---

## INTRODUCTION

PRT® is a wrap-around, heat shrinkable tubing that provides the same high performance characteristics of solid heat shrinkable tubing with the installation ease and time savings associated with an electrical wrap. PRT® eliminates electrical harness disassembly problems classically associated with a shrink tubing repair or modification by eliminating the need to slide the tubing over the end of the wire. PRT® can be used to provide additional chemical, mechanical, electrical or thermal protection to a wire or cable. It provides operational longevity comparable to standard shrink tubing while minimizing installation and down time.

## SIZING CHART



### CAUTION

Prior to beginning any work on production assemblies, it is suggested that installers read the instructions closely and practice using this material on mockup assemblies. Personnel familiar with installing heat-shrinkable tubing will be aware of some of the general do's and don'ts when installing these types of materials. However, working with a split heat-shrinkable material and a pressure-sensitive adhesive presents different handling requirements from standard tubing. Ideal results will be obtained by closely following the installation procedure.

### STEP 01

### SIZING

Measure the outside diameter of the wire or cable to be covered with PRT® using a caliper or micrometer. Use [Table 1](#) and find the measured cable diameter. Select the corresponding PRT® tubing size. If your cable OD is within 0.020 inches (0.5mm) of the high end of a cable size range, it is recommended that you select the next larger PRT® size. A larger size will yield a jacket with the least residual stress and still be snug on the cable when fully shrunk.

**Note:** Selecting a PRT® tubing size smaller than recommended may result in the material opening up during the heating process.

TABLE 1: PRT® Sizing Chart<sup>1</sup>

PRT® Size	Cable Diameter Inches (mm)	PRT® Size	Cable Diameter Inches (mm)
0	0.090 - 0.124 (2.3 - 3.2)	8	0.88 - 0.99 (22 - 25)
1	0.125 - 0.187 (3.2 - 4.8)	9	1.0 - 1.12 (25 - 29)
2	0.188 - 0.249 (4.8 - 6.3)	10	1.13 - 1.24 (29 - 32)
3	0.25 - 0.37 (6.3 - 9.5)	11	1.25 - 1.37 (32 - 35)
4	0.38 - 0.49 (9.5 - 13)	12	1.38 - 1.49 (35 - 38)
5	0.50 - 0.62 (13 - 16)	13	1.50 - 1.62 (38 - 41)
6	0.63 - 0.74 (16 - 19)	14	1.63 - 1.74 (41 - 44)
7	0.75 - 0.87 (19 - 22)	15	1.75 - 1.87 (44 - 48)

<sup>1</sup> For cable diameters beyond Table 1, contact Zippertubing's Engineering department

## INSTALLATION

STEP  
**02**

### PREPARATION

Cut the PRT® from the spool or roll as needed using standard scissors. Wrap the tubing around the wire or cable so the paper release liner faces the installer. Peel back a short portion of the release liner (not all) and expose the adhesive. Position the non-adhesive edge of the tubing over the exposed adhesive section and align so all the adhesive is covered but no more. Never over-wrap the tubing leaving a loose flap of material at the overlap. Doing so could result in an undersized tubing condition and lead to the tubing tearing apart during the heating process. Begin bonding the tubing overlap edge to the adhesive. Avoid contacting the adhesive with your fingers as much as possible. Remove short sections of the release liner until the entire tubing length is sealed closed. Rub the overlap seam area firmly using your thumb to work out any wrinkles. Minor wrinkles will disappear when the tubing shrinks. (Photo 1)



Photo 1: Installing PRT® around the cable

**Note:**

- a) When PRT® is removed from the original spool it may have a flat profile with creased edges. Do not be alarmed by this shape, it will disappear when the product shrinks.
- b) If the material was pre-cut into pieces or not stored on the original spool you may find that the material has curled up along its longitudinal axis. This is common for sizes of 3/8 inch or less. This material is usable and can be unrolled and installed as described above. All tension will be relieved once the material shrinks. Store pre-cut pieces in a flat condition to minimize curling.

STEP  
**03**

### POSITIONING

Position the PRT® on the wire, cable or bundle as desired. The easiest way to install is to locate the tubing's overlap seam so it faces the installer. Keep in mind that the tubing's wall thickness at the overlap area will be twice as thick, so orientating it to face areas susceptible to chaffing or abrasion could be desirable. If abrasion is not an issue but cable bending is, then the overlap seam should be located on the outside of the radius so the thin wall section is on the inside.

**Note:**

- a) Do not be concerned over the size of the tubing versus the wire size. It will always appear larger.
- b) You may shrink the tubing in place immediately after sealing. The adhesive has no cure time.

STEP

04

## SHRINKING

**Tools for installation (recommended):** Heat gun (500° to 750°F), reducer nozzle, and gloves.

PRT® tubing begins to shrink at 194°F, however to achieve a timely and uniform installation, it's desirable to use a heat gun temperature setting of 248-266°F. Always use a small reducer nozzle that will allow you to localize the heat stream (Photo 2). Never use a tubing reflector designed to spread the heat evenly or an infrared-type of heat gun.

**a)** Begin shrinking PRT® by directing the heat source at the adhesive overlap area near the center of the tubing (Photo 2). Apply heat to the adhesive overlap area only. The overlap area will tend to curl up into a "U" shape as it is heated (Photo 3). Continue applying heat in short bursts to this area until the surrounding tubing begins to pull the "U" shape back down flat. Do not be afraid to apply extra heat to the overlap area, as it will take extra dwell time for the inside layer of the overlap to shrink. Do not be alarmed if the outer layer of the overlap flap tends to lift off the adhesive and curl back slightly during initial heat exposure. With continued heating this lifted area will generally lay back down on its own. If not, lightly tap the lifted edge as necessary with a wooden popsicle stick. Shrink the overlap seam area along its entire length before making any attempt the shrink to remaining tubing.

**b)** After the overlap seam has fully shrunk, begin applying heat to the remaining tubing. With small diameter tubing sizes you may find that most of the remaining tubing has already shrunk. Visually examine the entire circumference of the tubing and apply localized heat to any areas that show evidence of insufficient heating. While the tubing is hot you may work or form the PRT® tubing and cable as necessary. Once properly positioned allow the finished assembly to cool to the point of being warm.

**c)** The finished assembly may display a shiny, sticky area, parallel to the overlap seam. This is residual adhesive that was exposed as the overlap material pulled back during shrinking. The excess adhesive can be removed while the tubing is warm by rubbing your thumb along the overlap seam line. Rubbing the seam area will ensure good overlap contact and the excess adhesive will ball up ahead of your thumb. Remove excess adhesive as necessary and discard (Photo 4 & 5).



Photo 2: Heat gun with reducer nozzle



Photo 3: Overlap seams curled up prior to full shrinkage.



Photo 4: Rubbing adhesive seam after shrinking.



Photo 5: Residual adhesive ball



**CAUTION: DO NOT attempt to remove excess closure adhesive using solvents. Tubing and adhesive will be hot. Use gloves to form tubing and remove adhesive or allow tubing to cool before handling.**

## TROUBLESHOOTING



### TROUBLESHOOTING

1. The most common problem likely to occur when installing PRT® is an overlap seam rupture. This is a condition where the overlap seam pulls apart during installation. Seam ruptures are most likely to occur during the learning phase of PRT® installations. Once the proper installation technique has been mastered this problem will disappear. Rushing to complete an installation is a big factor in creating a seam rupture.
2. Seam ruptures occur for two reasons and are controllable by the installer:
  - a) Incorrect size: The PRT® tubing selected was too small for the cable diameter being repaired.
  - b) Excessive Heat: Too much heat was applied too quickly.
3. If a rupture does occur, the tubing must be replaced. Verify that the tubing size was correct. If correct, then adjust the heating technique by applying heat slowly and evenly. Minimize heat exposure to the tubing beyond the overlap flap. Use a “sneak up on it” approach where the heat is repeatedly removed from the tubing for a few seconds allowing it to cool and then re-apply. In awkward installations, a piece of aluminum foil can be useful as a heat block to blind the heat from the surrounding area.

**Installer Note:**

Using the PRT® tubing repair method will generally eliminate a large amount of cable harness disassembly and rework time. As a result, don't be in a rush to complete the installation. Take the few extra minutes to plan the installation, heat the sleeve slowly, and work the materials as necessary to ensure a good first time repair. The extra time spent doing this will be small in comparison to the time required to perform a classic repair that involves connector disassembly.

**NOTES**


A series of horizontal dotted lines for writing notes, spanning the width of the page.

**ZT**<sup>®</sup>  
zippertubing

 7150 W. Erie St., Chandler, AZ 85226

 [sales@zippertubing.com](mailto:sales@zippertubing.com)

 [zippertubing.com](http://zippertubing.com)

 (855) 289.1874