


WHITE ELASTOMERIC OVER METAL

Guide : RX-ME-500



GENERAL

ROOF X TENDER® Guide RX-ME-500 is a maintenance system designed for use over metal roof systems. It provides a cool and energy efficient system designed to reduce roof temperatures and extend the service life of metal roofs. All preparation, repairs of damage including cleaning, rust removal, fastener replacement, seams, flashings, etc., must be completed prior to application of coating. Comply with all safety and fall requirements as recommended by OSHA. Always follow good roofing practices as recommended by NRCA. Roofs must maintain positive drainage. Always verify weather conditions before, during and after application (temperatures, humidity, wind and precipitation). Check and follow individual product directions for specific application and installation requirements on product data sheets, labels and SDS sheets. Gutters are not addressed and are not part of this guide. This is a summary sheet. For job specific requirements and specifications consult with an architect, engineer, roof consultant or design professional.

ENERGY COMPLIANCE:

Energy Star, CRRC

MATERIAL QUANTITIES

Self Adhered Butyl	Seams	As needed
Polyester	Seams	As needed
RX-705	Fastener heads Seams	1 dob per screw/fastener As needed
RX-500	First coat	1.5 gallons per square
RX-500	First coat	1.5 gallons per square
Total RX-500		3 gallons per square
Optional Rubber Seal (required for extended warranty as noted in Step 4)		
RX-300	Rubber Seal WB	3 gallons per square

INSTALLATION

STEP 1 - Metal repairs

- Replace metal panels that are badly rusted or damaged.
- Replace missing or stripped fasteners.
- Tighten all loose fasteners.
- Replace missing foam closures.

STEP 2 - Flashing details

- Coat each fastener head with a dob of RX-705.
- Seal all horizontal lap seams with 6" wide SA butyl polyester faced tape.
- Seal vertical lap seams with a 4" wide SA butyl polyester faced tape.
- Seal metal flanges, walls and ridge with 6" wide SA butyl polyester faced tape.
- Reinforce pipes and angles with a wrap and target of SA butyl polyester faced tape.
- (Optional) As a replacement for SA butyl tape, contractor may use three course of RX-705 and polyester (of same width, 3 oz min) for flashing details.

STEP 3 - Surface prep

- Wire brush loose surface rust.
- Prime all cleaned rust areas with rust inhibitive primer.
- Power wash and scrub with soft broom or mop to remove dirt and grime.
- Tape off and shield all surfaces which are not to be coated.
- Allow all surfaces to dry prior to coating.

STEP 4 - Protect and reflect

- Base coat - (Optional) Apply Rubber Seal RX-300 at the rate of 3 gallons per square.
- First coat - Apply RX-500 at the rate of 1.5 gallon per square.
- Second coat - Apply RX-500 at the rate of 1.5 gallon per square.