

Whittle CNC

Big Results

Assembly Instructions

Last Updated: 12/12/2016

Table of Contents

| | |
|---|-----------|
| Step 1: Z-Axis | 4 |
| Step 2: X-Shuttle | 6 |
| Step 3: Y-Shuttle Right Side | 10 |
| Step 4: Y-Shuttle Left Side | 12 |
| Step 5: Base Left Rear | 14 |
| Step 6: Other 3 Bases | 16 |
| Step 7: Bases to Frame | 17 |
| Step 8: Z-Shuttle to X-Shuttle | 19 |
| Step 9: X-Shuttle to Y-Shuttle | 21 |
| Step 10: Gantry to Frame | 23 |
| Step 11: Belts | 25 |
| Step 12: Power Supply & Back Board | 31 |
| Step 13: Feet | 33 |
| Step 14: End Stops | 35 |
| Step 15: Wiring | 37 |
| Step 16: Attaching Flex Shaft to Rotary Tool | 42 |
| Changing Bits | 45 |
| Bit Types & Uses | 47 |
| Recommended Settings/Speeds | 48 |


The shafts have one Cut side (A) and one Sanded side (B).

Only push the sanded side (B) through bearings.

A



B



Step 1

Parts List

Bag #1

Flex Shaft


Z-Shuttle



**Insert the bearings into
the bottom of the Z-
Shuttle.**



Insert 2x 10mm Bolts into each side of the Z-Shuttle and secure with Hex Nuts.



Insert 3x 20mm Bolts into the front of the Z-Shuttle and secure with 3x Hex Nuts.



Step 2

Parts List

Bag #2

1x Stepper Motor


X-Shuttle




Attach the Belt Pulley to the Stepper Motor. *Make sure the set screw is against the flat side of the shaft.*



Insert Bearings into the X-Shuttle.




Secure bearings with 4x 10mm bolts and 4x hex nuts. *Do not fully tighten at this point.*




Secure the Stepper Motor to the X-Shuttle using 4x 10mm hex bolts.



Orient the Motor so the wires are facing up.




**Insert the Belt
so it goes
around the Belt
Pulley.**



Place the bearing against the belt and push into place.



**While holding the bearing in place
insert the 1/4"x1" bolt and tighten.**



Parts List


Bag #3

Y-Shuttle Right

Step 3



Insert the bearing and secure using 4x 10mm bolts and 4x hex nuts.




Take the 1/4"x1" bolt and place the larger washer, bearing, and smaller washer on it.



Install the unit from the previous step on the rear of the Y-Shuttle Right. Do not over tighten.

Install the remaining screw on the bottom of the Shuttle (*Updated to a Black Screw*).



Parts List

Bag #4


1x Stepper Motor

Y-Shuttle Left

Step 4



Insert the bearing and secure using 4x 10mm bolts and 4x hex nut.



Install the Stepper Motor using 4x 10mm bolts. *Orient the motor so the wires are pointing up (away from the bearing).*



Attach The Pulley to the Motor Shaft Ensuring the bolt is against the flat part of the shaft (not pictured)

Step 5




Parts List

Bag #5


1x Stepper Motor

Left Rear Base

Attach the Pulley to the Stepper Motor.



**Attach to base to the
Motor Using 2x
10mmM3 bolts.**



Step 6

Parts List


Bag #6

3x Remaining Base Pieces

Start the 1x Screw into the top of a base section. Then Insert 1x Large Washer, 1x Bearing, 1x Small Washer, and 1x Large Washer. Then screw the screw completely into the base.



Be Sure not to over tighten as this will bind the bearing.



Step 7


Parts List

Bag #7


Black Frame

3x Parts from Step 6

Part from Step 5



Insert 2x Screws into the top of each base and secure with 2x Nuts.



Attach all 4 Base sections to the frame with 4x 14mmM3 and secure with hex nuts. Insert the Bolts into the underside of the frame. (*The underside has countersunk holes*)


Front Left




Front Right



Rear Left



Rear Right



Step 8



Parts List

2x 100mm Rods

X-Shuttle

Z-Shuttle


**Push the Z-Shuttle onto
the Belt.**

It will be snug.



**Insert the Rods in the X-Shuttle Securing the
Z-Shuttle.**

***For rigidity, these will be very snug. They will take some
working to get in.***



Step 9



Parts List


Previous Step Part

2x 300mm Rods


Y-Shuttle Left

Y-Shuttle Right


Insert the Rods Into the Y-Shuttle Left.



Slide the X-Shuttle onto the Rods.



Attach the Y-Shuttle Right to the Rods.



Step 10

Parts List

Frame


2x 400mm Rods

Previous Step Part


Insert the Rods Partially. Around 70%.



Slide the X-Shuttle onto the Rods.



Push the Rods Completely In and Tighten all 4 Sets of Base Clamp Screws. *(The Screws that tighten the clamps on the Rods)*



Step 11

Parts List

Belt Bag


WhittleCNC

Zip Tie Bag



Belts are a longer then needed and will require cutting to size after everything is connected and working.

Below is an overview of where the three different belts will go.




Take all 3 Belts and Zip tie one end as shown.



Insert the shortest belt into the Rear Side of the X-Shuttle.




Wrap the belt around the pulley and bearing and zip tie the end of the belt so it is $\frac{1}{4}$ " from the other end. Zip tie the ends together.




Take the medium length belt and repeat the previous step on the left size of the WhittleCNC. *(The Y-Motor Side)*




Take the longest belt and attach it to the previous belt in the following configuration.




Feed the belt through all four sides of the WhittleCNC and secure the end to the previous belt. It will be secured to the side that the current belt is not already attached to. So the zip ties will criss cross.




Push the **Gantry** all the way to the back and move the Zip Tied **Belts (Pictured Above)** all the way to the front.



Tighten the **Set Screw** on the Left Side of the Gantry to the Belt.



Push the **Gantry** all the way to the front. Now tighten the right set screw.



Step 12

Parts List


Bag #8

Power Supply


Frame Back



Secure the Power Supply to the Back on the Frame. *The Power Supply will be to the left of the Frame back when oriented correctly. Due to updates, you may have two sets of Bolts to Attach the Power Supply to the Frame. If one set is too short use the other provided set. (4x14mm & 4x16mm)*



Use 2x 20mmM3 bolts to attach the Back to the Frame.



Step 13

Parts List


WhittleCNC

Bag with Feet

Cutting Bed



Insert the 8-32 x 3" Screws into the 4 holes of the frame.



Attach the feet to the bottom of the Screws.



Step 14


End Stops

Parts List

WhittleCNC
Bag with End Stops

Install the End Stops as Shown Below.


X Axis





Z Axis



Y Axis *(This End Stop switch comes pre wired)*



Push on the connectors for the Z and X End Stops



Step 15

Wiring

Parts List

Bag #8

Control Board

Fan


Connect the control board to the Power Supply in the following configuration: 8mmM3 bolt, Control Board, Spacer, Power Supply at the #1 location.

Secure the Other Side (#8) Using the Adhesive Support
Connect the fan to the Power Supply using 20mmM3 bolt at the #2 location.

Attach wire connectors to the following locations:

- 3. Z-Axis Motor
- 4. Y-Axis Motor
- 5. X-Axis Motor
- 6. Power Supply Wire
(Black Left, Red Right)
- 7. Fan
(Lower two Pins Pictured)

Detailed connection guide on
Page 41.




Ensure the correct supply
voltage is selected using a small screwdriver.




Attach wires to the following locations:

1. Control Board Red Wire
2. Control Board Black Wire
4. Power Cord Black or Brown
5. Power Cord White or Blue
3. Power Cord Ground




Take two zip ties and bend them as shown



Push them Into the power supply and pull them through.




Secure the flex shaft to the power supply as shown.



Adjust the potentiometers (dials) on the boards so the flat part lines up with the yellow lines below.

This is the general area they will need to be set and can be adjusted for more or less power to the motors.



*****Never Disconnect Stepper Motors when the Board Has Power. This WILL destroy the 3 Stepper Motor Drivers.*****

Please Note the End Stop Printed Labeling is incorrect. From top to bottom the connections are Z,Y,X as shown in the image above. The Z and X labels are switched.

Step 16

Parts List

Rotary Tool

Flex Shaft




Remove the ring from
the collar of the
Rotary Tool



Pull the Shaft Out 2"
from the Flex Shaft



Insert the Shaft into the Rotary tool and Tighten the Black Collar.



Push the Flex Shaft onto the Rotary tool and Tighten the shaft.



Assembly is now Complete!

**For a detailed guide on how to connect
your WhittleCNC to Easel and your
Computer please go to**

<http://www.whittlecnc.com/pages/support>
“Driver Installation & Easel Setup”

****Please remember to monitor the rotary tool and give the
tool breaks to cool down if the motor is getting too hot.
Depending on your location and environmental conditions it
may need a break during cut jobs.****

Changing Bits

Parts List

Starter Bits

Flex Shaft


Wrench

Shaft Tool



Insert the Shaft Tool into the hole on the End of the Flex Shaft.

There is an interior hole on the shaft that you can lineup by rotating the shaft.



Insert the Bit



Use the wrench to secure the bit.



Bit Type & Recommended Uses



Ball Nose End Mill

Ball nose (aka contouring) bits are fantastic for 3d carving.. You can carve with just the tip to get great detail and smooth contours or they can move a lot of material just like an end mill.



Burr End Mill

They're great for finishing cuts, but their material removing capacity is limited relative to other kinds of bits. Since they're gentle on the material, they are often used with composites, PC board material, and other layered materials.



Fluted Bit

Great general use bit for many material types and great chip removal. Remember to slow down your cut speed as more material is being removed per pass.



V-Bit

If you want to do lettering or detailed sign making, you'll need to get a v bit. These are sometimes called v-carving bits, v-groove bits, or engraving bits. This is the only way to get a sharp grooved bottom on the inside of those roman numerals.

Recommended Starter Settings

You can increase speeds as you become more familiar with your machine!

| Material | Feed Rate | Tool Speed | Cut Depth |
|--------------------------------|---------------------------|------------|-----------|
| Aluminum | 40 mm/min | High | 0.2 mm |
| HDPE | 355 mm/min | Low | 1 mm |
| Polycarbonate | 600 mm/min | Medium | 1 mm |
| Acrylic | 400 mm/min | Medium | 1 mm |
| Plywood | 500 mm/min | High | .7 mm |
| MDF | 700 mm/min | High | 1.5 mm |
| Foam "Starter Material" | 800 mm/min (conservative) | High | 2 mm |