Anti-moisture Weighing Scale

Service Manual

TABLE OF CONTENTS

INSTRUCTIONS FOR USE	2
PREPARATIONS BEFORE USING	2
DISPLAY DESCRIPTIONS	3
SYMBOL INDICATION	
AVAILABLE UNITS	3
KEYPAD DESCRIPTIONS	4
Counting Function	5
EXTERNAL FUNCTIONS	5
00 FNC: Function Setting	6
01 FN1: FILTER SETTING AND AUTOMATIC POWER-OFF TIMER SETTING	6
02 EC: EXTERNAL WEIGHT CALIBRATION	7
04 HI: HIGH LIMIT VALUE SETTING	8
05 Low: Low Limit Value Setting	8
06 uEn: Units Selection	8
11 SER: PRODUCT SERIES NUMBER	9
12 VER: PROGRAM VERSION	9
13 AdC: Internal Value Display	g
POWER SUPPLY	10
POWER SUPPLY SELECTION	10
POWER CONSUMPTION	10
LOW BATTERY WARNING	10
ERROR MESSAGES	10
INTERNAL FUNCTION	11
01 CSP: Specifications Setting	12
02 CAL: WEIGHT CALIBRATION	13
03 CLN: LINEARITY CALIBRATION	13
06 CGR: Acceleration of Gravity Calibration	14
07 RMP: PERFORMANCE OF ALL LOAD CELLS TRENDS TO CONSISTENTLY	14
APPENDIX 7-SEGMENT DISPLAY CHARACTERS	15

Thank you for purchasing EXCELL Anti-moisture Weighing Scale. In order to operate smoothly, to last the durability, and to reduce the chance of breakdown for this product, please read this Manual carefully.


Instructions for Use

- 1. Please keep the scale clean and free from insect infestation.
- 2. To avoid impact and it is to be used under designated pressure (the weight put on the platter can not exceed the maximum capacity of the scale).
- 3. If the scale is not going to be used for some time, please clean it and store it in a plastic bag in dry condition. A desiccant sachet may be included to prevent moisture build up. The scale should be recharged every 3 months to prevent failure of the internal rechargeable battery.
- 4. The commodity should be placed at the centre of platter for accurate weighing. The dimension of the weighted commodity should not exceed the dimension of platter.
- 5. Any suggestion is warmly welcome.

Preparations before Using

- 1. Put the scale on a firm level surface free for accurate weight readings. Adjust the four leveling feet to get the leveling bubble at the centre of circle.
- 2. Scale must be used under a stable temperature and stable air flow. Avoid direct sunlight onto the scale or near the exhaust port of ventilating system.
- Scale must be used under individual socket to avoid the interference of other electric appliances.
- 4. Remove any weight that might be on the platter before the scale is switched on.
- 5. Please note that when or symbol appears on the screen, the scale needs to be recharged.

Display Descriptions



Symbol Indication

→0← : Zero Indication.
NET : Net Indication.
kg : "kg" unit.
lb : "lb" unit.

斤: "Taiwan Catty" unit.

Pcs: Press this key to enter into counting mode.

: When the power indication turns to be low battery or even less, it means

that battery should be recharged immediately.

▼1 : (STABLE) ▼2 : (GROSS)


■ Signification:

■ The state of the state

Available Units

kg	1g = 0.001 kg	GN	1g = 15.432358 GN
g	1g = 1g	ct	1g = 5ct
TW Catty	1g = 0.02666667 TW Tael	dwt	1g = 0.6430149 dwt
lb	1g = 0.002204623 lb	pcs	
oz	1g = 0.03527396 oz	viss	1kg = 0.612245 viss

Keypad Descriptions



Remark: The blank key only works under the calibration mode.

1. **OFF**: Press this key to turn off the scale.

2. ON/ZERO

When the scale is off, press this key to power it on.

When the scale is on, press this key to back to zero.

When calibration, press this key to increase the parameter value.

- When there are not any commodity on the platter, the display is not showing, press this key to zero the scale. At zero, the " \rightarrow 0 \leftarrow " indication is on.
- Zero range: ± 2% of full scale
- **3. TARE** : (Move the cursor rightward)

Put a container on the platter and after the weight is stable, press this key to zero the weight of the container. The screen displays the "Net" icon.

Put the commodity on the container, the display shows the net weight value of the goods.

Remove the full container, the display shows the negative weight value of the container.

Then press TARE again to cancel the tare operation and the scale reverts back to zero. The "Net" icon is switched off.

- Continuous tare operation is adding tare objects on platter and pressing the Tare key each time
- Continuous tare range = full weighing capacity of the scale
- **4. UNITS**: Press **UNITS** key to select weighing units or counting units. It displays the symbol of weighing unit or the counting unit "Pcs". After power off, the scale will memorize the active unit. When calibration, press the key to decrease the parameter value.

5. NET/GROSS : (Move the cursor leftward)

In Tare mode, press **NET/GROSS** key once to display gross value. Net symbol disappears, and the gross value "▼" appears. Press **NET/GROSS** key again, it displays net value, the indication **NET** appears and the gross value indication disappears. Press **NET/GROSS** key continually to display net value or gross value. The **NET/GROSS** key is only used in Tare mode. When "▼" gross icon is on, only **NET/GROSS** key is functional.

Counting Function


- ◆ Press **UNITS** key to enter into counting mode. Press **NET/GROSS** key to switch counting sampling size 10, 20, 50, 100 and 200. The LCD shows C10, C20, C50, C100, and C200 in sequence.
- Put enough sample on the platter as need.
- After the sampling process is stable, press the UNITS key to enter into the counting mode and the screen shows the quantity of items.

Insufficient Sampling size (): Total weight of samples is less than 20d. (d=division) Insufficient Unit Weight (): The shown quantity is less than 1 PCS.


If displays, the scale would be out of sampling mode and enter into the "unit" mode.

External Functions

Press and hold on **ON/ZERO** while turning on with countdown to enter into the External Function setting mode.



00 FNC: Function Setting



* The scale will not work normally with meaningless input value.

Column

A: Backlight Control

0=Backlight Off 1=Backlight On

2=Auto-Backlight

When the weight is over 10d or keys are pressed, the display backlight will be on. After the weight is stable for 10 seconds (the weight is less than 10d or it's negative value) or when the scale returns to zero, the display backlight switches off.


B: Resolution shift

0=Low resolution 1 / 3 000 (Default setting)

1=High resolution 1 / 6 000 (High resolution 1/7 500 for 1.5 kg and 15 kg model)

Press confirmation key after finishing setting.

01 FN1: Filter setting and automatic power-off timer setting



Column

A: Environment Parameter Filter Adjustment

Set different stable parameter for different environment. The order of parameters is 0, 1, 2, 3.

Suggestion:

The smaller number of parameter is better for worse environment.


B: Automatic power-off timer setting

The function of automatic power-off timer setting is selectable to switch on when the weight is empty on the platter and no key is operated.


Setting range: 1~9 Min.

- 0: No auto power-off
- 1: When the scale is idle for 1 minute, the scale automatically switches off
- 2: When the scale is idle for 2 minute, the scale automatically switches off

02 EC: External Weight Calibration




04 hi: High Limit Value Setting



Press confirmation key after finishing setting.


05 Low: Low Limit Value Setting



Press confirmation key after finishing setting.

Display "OK" when the weight value is between "HI" and "LO" of setting values.

06 uEn: Units Selection



Column

A: Select units as follows:

0=kg 1=g 2=twg 3=lb 4=ounce 5=grain 6=carat 7=dwt

8=Pcs counting mode 9=viss (in Myanmar)


Press **ON/ZERO** key to increase the number of the flashing digit. Press **UNITS** key to decrease the number of the flashing digit.

B: Weight unit is active or inactive.

(0= the weight unit is active. 1= the weight unit is inactive)


Press **NET/GROSS** key and then show "0", the unit is inactive. Press **TARE** key and then show "1", the unit is active.

11 SEr: Product Series Number




Show the product series number of the scale.

12 VEr: Program Version



Show the program version number of the scale.

13 AdC: Internal Value Display



Show the internal value of the scale.

Power Supply

Power Supply Selection

- 1. 6V/5Ah rechargeable battery
- 2. Adaptor: Output DC 10V 1A

Power Consumption

Power consumption is less than 3 mA when the scale is powered-off.

Power consumption after the scale is powered-on:

	Backlight on	Backlight off
One-sided display	About 42 mA	About 29 mA
Double-sided display	About 56 mA	About 30 mA

Low Battery Warning

When the power indication turns to low battery or even less, it means the battery should be recharged immediately.

The scale will power off automatically after several hours and enter into self-protection mode of battery. The scale can be only used again with full recharged battery.

Note: When the battery voltage is less than 5.4 V, the scale would power off automatically.



Battery voltage is more than 5.8 V.



Battery voltage is about 5.7 V.



Battery voltage is about 5.5 V.



Battery voltage is less than 5.44 V.

Error Messages

E0: EEPROM is unable to be read.

E1: Zero value is higher than Calibration Zero value +10%.

E2: Zero value is lower than Calibration Zero value -10%.

E3: Calibration data is error.

E4 : Internal value is unstable.

E5: The AD value is 0.

E6 : Calibration Zero is excessively low.

E7: Calibration Zero is excessively high.


E8: Calibration Resolution is excessively high.

OL: The weight value is over the capacity + 9e.

Internal Function

Switch mini jump to ADJ location before the operation of internal calibration setting and switch it back to LOCK after setting finished. The setting operation can be stopped during process by shutting the scale off.

Internal calibration operation and parameter description



01 = Specification Setting

02 = Weight Calibration

03 = Linearity Calibration

06 = Acceleration of Gravity Calibration

07 = Performance of all load cells trends to consistently

Internal Calibration Order:

07 RMP (After the first storage of program, this calibration must be done when the scale_is powered on)

01 CSP (Set full capacity of scale)

03 CLN (Linearity calibration setting)


02 CAL(Weight Calibration)

06 CGR (Acceleration of Gravity Calibration)

01 CSP: Specifications Setting

Press confirmation key to enter into as follows.

WEIGHT



Column:

А	Capacity	Division	
0	1.5000 kg	0.2 g / 0.5 g	
1	3.0000 kg	0.5 g / 1.0 g	
2	6.000 kg	1 g / 2 g	
3	15.000 kg	2 g / 5 g	
4	30.000 kg	5 g / 10 g	


Resolution: 3 000 / 6 000 can be changed by external FNC.

02 CAL: Weight Calibration

Press confirmation key to enter into as follows.



When there are no commodities on the platter, press confirmation key to read and record no weight.



Put weights on the platter to reach full capacity of scale, and then press confirmation key to read and record the Full capacity.

According to the specifications selected, the screen displays the weights needed.

"1.5 kg" shows 01500.0

"3 kg" shows 03000.0

"6 kg" shows 006.000

"15 kg" shows 015.000


"30 kg" shows 030.000

03 CLN: Linearity Calibration


Press confirmation key to enter into as follows.




When there are no commodities on the platter, press confirmation key to read and record no weight.



Put weights on the platter to reach 1/3 full capacity of scale, and then press confirmation key to read and record the 1/3 full capacity.



Put weights on the platter to reach 2/3 full capacity of scale, and then press confirmation key to read and record the 2/3 full capacity.



Put weights on the platter to reach full capacity of scale, and then press confirmation key to read and record the Full capacity value.

Please redo weight calibration after doing the linearity calibration.

06 CGR: Acceleration of Gravity Calibration

Press confirmation key to enter into as follows.

WEIGHT



Default acceleration of gravity is 9.79425.

The digits of WEIGHT: Acceleration of gravity in using place.

The acceleration of gravity value should be between the gravity values of equator standard and polar standard.

Equator standard gravity $G_E = 9.7803184558 \text{ m/sec}^2$

Polar region standard gravity $G_P = 9.8321772792 \text{ m/sec}^2$

Taipei $= 9.78914 \text{ m/sec}^2$

Shanghai $= 9.79423 \text{ m/sec}^2$

07 RMP: Performance of all load cells trends to consistently

Press confirmation key to enter into as follows.

WEIGHT





Press confirmation key when the platter is empty, then the value will be run from 0000 until it would be shown.





Put weights on the platter to reach full capacity of scale, then press confirmation key. The value will be run from 0000 until it would be shown.



Remove weights from the platter and press confirmation key to back to functional option.

Appendix 7-Segment Display Characters

Number	Display	Letter	Display	Letter	Display
0		А		N	8
1		В	В	0	Œ
2	8	С		Р	
3	8	D	3	Q	
4		E	Ξ	R	
5		F	Ξ	S	
6		G	В	Т	Π
7	В	Н	В	U	
8		-	В	V	
9		J		W	
		К		Х	
		L		Y	8
°C	88	М	8	Z	8