

The 5000 Series.

- **Pre-assembled masks:** 5104 (FFA1) 5161/5164 (FFA1 P1D) 5174 (FFA1 P2D) 5274 (FFABE1 P2D)
5504 (FFA2), 5584 (FFA2 P3D) 5901/5904 (ABEK1) 5981/5984 (ABEK1 P3D)
- **Particulate Filter Discs:** 8060 (P1 D) 8070 (P2 D) 8010 (P2 SD) 8080 (P3 D) 8030 (P3 SD)
- **Particulate Filter Holders:** 8090 / 8025

Characteristics

"The 5000 Series" masks from Moldex are convenient and easy to use. Supplied pre-assembled for use in most gas and vapour applications, these effective, disposable respirators combine high performance with the minimum of maintenance and no requirements for record keeping. Purpose designed for enhanced wearer comfort and improved field of vision, the 5000 series masks are lightweight and easy to fit. Gas filter cartridges permanently mounted to the facepiece with built in inhalation valves provide gas and vapour protection.

Replaceable particulate filter discs provide dust, mist and fume protection where required. Improved clogging characteristics enable particulate filters to pass the dolomite clogging test (D).

Construction / Materials

5000 Series respirators are made of:

- Facepiece = Polypropylene, Kraton
- Head Strap = Polyester, Natural Rubber
- Clip = Polyethylene
- Particulate Filter = Polypropylene
- Particulate Filter Holders = Polypropylene
- Gas Filter = Activated Carbon
- Gas Filter Cartridges = Polypropylene
- Inhalation Valve = Natural Rubber, SBR
- Exhalation Valve = Synthetic Rubber

Weights:

FFA1:	5104:	219 g	
FFA1 P1D:	5161:	242 g	5164: 249 g
FFA1 P2D:	5174:	250 g	
FFABE1 P2D:	5274:	257 g	
FFA2:	5504:	254 g	
FFA2 P3D:	5584:	346 g	
FFABEK1:	5901:	259 g	5904: 266 g
FFABEK1 P3D:	5981:	353 g	5984: 360 g

Certification

The Moldex 5000 Series meet the requirements of EN405:2001, EN143:2000 and *EN143:1990 and are CE marked in accordance with the requirements of European Directive 89/686/EEC.

The *Berufsgenossenschaftliche Institut für Arbeitssicherheit* (BGIA) in St. Augustin in Germany is the body responsible for both type examination (Article 10) and monitoring of production (Article 11).

The products are manufactured in an ISO 9001: 2000 certified plant.

Gas / Vapour hazards:

LEVEL (FILTER)	Max. Use Level*	HAZARD TYPE (EXAMPLE)
FFA1	10 x WEL or 1000 ppm	ORGANIC GASES/ VAPOURS b.p. > 65 degrees C (Against solvents from Adhesives, Paints, Paint Sprays, Pesticides)
FFABEK1	10 x WEL or 1000 ppm	ORGANIC GASES/ VAPOURS b.p. > 65 degrees C (Against solvents from Adhesives, Paints, Paint Sprays, Pesticides), INORGANIC GASES AND VAPOURS (Against chlorine, bromine, hydrogen cyanide, hydrogen sulphide), ACID GASES (Against hydrogen chloride, nitric acid, sulphur dioxide) and AMMONIA AND AMINE DERIVATIVES
FFA2	10 x WEL or 5000 ppm	ORGANIC GASES/ VAPOURS b.p. > 65 degrees C (e.g. As for A1 but at higher concentrations)

* whichever is lower

(WEL = Workplace Exposure Level (ppm = parts per million)

Particulate hazards:

LEVEL (FILTER)	Max. Use Level	HAZARD TYPE (EXAMPLE)
P1 D (8060)	4 x WEL	FINE DUSTS, FUMES, WATER AND OIL BASED MISTS / AEROSOLS (Against non-toxic dusts, e.g. Aluminium Oxide, Bauxite, Borax, Brick Dust, Cellulose, Cement, Coal Dust, Gypsum, Limestone, Plaster of Paris, Pollen, Portland Cement, Sucrose, Sugar.)
P2 D (8070)	10 x WEL	FINE TOXIC DUSTS, FUMES, WATER AND OIL BASED MISTS / AEROSOLS (e.g. As for P1 but at higher concentrations, plus: Brake Dust, Calcium Oxide, China Clay, Concrete Dust, Cotton Dust, Granite, Hay, Lead Dust and Fume, Particulate Welding Fumes, Silica, Sodium Hydroxide, Wood Dust, Zinc Oxide Fume.)
P2 SD * (8010)	10 x WEL	FINE TOXIC DUSTS, FUMES AND WATER BASED MISTS / AEROSOLS
P3 D (8080)	20 x WEL	FINE TOXIC DUSTS, FUMES, WATER AND OIL BASED MISTS / AEROSOLS (e.g. As for P2 but at higher concentrations, plus: Ceramic Fibres, Chromates, Chromium, Cobalt, Nickel, Micro Organisms, Radioactive or Biochemical Active Substances.)

(WEL = Workplace Exposure Level)

* = EN143:1990

The 5000 Series.

Testing

The respirators of the Moldex 5000 Series have been tested to EN405:2001 and fulfill all requirements of the relevant categories. As the particle filters are separable and can be used with other devices, these are tested to EN143:2000 and *EN143:1990 for filter penetration performance.

• Inward leakage of facepiece

Ten test subjects wearing respirators perform a variety of exercises on a running machine. During the exercises the amount of test aerosol that penetrates the face seal and exhalation valve are sampled. The inward leakage of the test contaminant must not exceed a value of 5 % of the inhaled air with 46 out of 50 test exercises. 8 out of 10 average values must not exceed 2 % of the total inward leakage.

• Breathing Resistance

The breathing resistance produced by the gas filter cartridge or combination of gas filter cartridge and particulate filter disc is tested at an airflow of 30 l/min and 95 l/min.

CLASSIFICATION <input type="checkbox"/>	MAX. BREATHING RESISTANCE	
	30 l/min <input type="checkbox"/>	95 l/min <input type="checkbox"/>
A1 <input type="checkbox"/>	1,0 mbar <input type="checkbox"/>	4,0 mbar <input type="checkbox"/>
A1 P1D <input type="checkbox"/>	1,6 mbar <input type="checkbox"/>	6,1 mbar <input type="checkbox"/>
A1 P2D <input type="checkbox"/>	1,7 mbar <input type="checkbox"/>	6,4 mbar <input type="checkbox"/>
ABE1 P2D <input type="checkbox"/>	1,7 mbar <input type="checkbox"/>	6,4 mbar <input type="checkbox"/>
A2 <input type="checkbox"/>	1,4 mbar <input type="checkbox"/>	5,6 mbar <input type="checkbox"/>
A2 P3D <input type="checkbox"/>	2,4 mbar <input type="checkbox"/>	8,6 mbar <input type="checkbox"/>
ABEK1 <input type="checkbox"/>	1,0 mbar <input type="checkbox"/>	4,0 mbar <input type="checkbox"/>
ABEK1 P3D <input type="checkbox"/>	2,4 mbar <input type="checkbox"/>	8,6 mbar <input type="checkbox"/>

• Flammability

Masks are passed through a 800°C (+/- 50°C) flame with a speed of 6 cm/s. After passing through the flame the effect of the test on the mask components is noted.

• Protection Capacity

The minimum capacities and breakthrough times of the gas filter cartridges are tested at a flowrate of 30 l/min.

CATEGORY <input type="checkbox"/> TEST GASES <input type="checkbox"/>	MINIMUM <input type="checkbox"/> CAPACITY <input type="checkbox"/>	MINIMUM BREAK- THROUGH TIME
A1 <input type="checkbox"/> Cyclohexane <input type="checkbox"/>	7,3 g <input type="checkbox"/>	70 mins
B1 <input type="checkbox"/> Chlorine <input type="checkbox"/>	1,8 g <input type="checkbox"/>	20 mins
<input type="checkbox"/> Hydrogen sulfide <input type="checkbox"/>	1,7 g <input type="checkbox"/>	40 mins
<input type="checkbox"/> Hydrogen cyanide <input type="checkbox"/>	0,84 g <input type="checkbox"/>	25 mins
E1 <input type="checkbox"/> Sulfur dioxide <input type="checkbox"/>	1,6 g <input type="checkbox"/>	20 mins
K1 <input type="checkbox"/> Ammonia <input type="checkbox"/>	1,05 g <input type="checkbox"/>	50 mins
A2 <input type="checkbox"/> Cyclohexane <input type="checkbox"/>	18,4 g <input type="checkbox"/>	35 mins

INFO: For help on selection and training please contact us. We offer a wide range of training packages and support material.


MOLDEX-METRIC AG & Co. KG
Glaisdale Point
Off Glaisdale Drive Bilborough
Nottingham NG8 4GP


Phone 0115 985 4288
Fax 0115 985 4211
www.moldex-europe.com
sales@uk.moldex-europe.com


Instructions For Use


- The user has to be trained and instructed in wearing the respirator.
- These products do not protect against asphyxiants.
- The oxygen concentration of the ambient atmosphere must be at least 19.5 % Volume.
- These respirators may not be employed if the concentration, type and properties of contaminants in the ambient atmosphere are unknown or at dangerous levels.
- Respirators should be disposed off if damaged, if the set safe wear time is exceeded or if gas/vapour is detected inside the respirator by taste or smell. If used, particulate filters need to be exchanged if the breathing resistance becomes high due to clogging.
- Never tamper with, alter or modify the respirator.


Instructions For Fitting


- 

Place the respirator over mouth and nose, then pull head harness over the crown of the head.
- 

Hook up the bottom straps at the back of the neck.
- 

Pull the ends of the head harness and bottom straps to the required tightness. Check that a tight seal is formed between face and mask before entering the work area.
- 

Positive pressure facefit check: Place the palm of the hand over the exhalation valve and slowly breathe out. If the mask forms a good seal, then no air should escape between the mask and the face. Adjust and repeat if leakage occurs.
- 

Negative pressure facefit check: Place the palms of the hands over the cartridges and breathe in slowly. If the mask fits securely, the facepiece should contract slightly, pulling towards the face. Adjust and repeat if inward leaks occur.
- 

MOLDEX