





THE SSC CONTROLS COMPANY

PREMIER INDUSTRIAL CONTROLS

Wiring Diagram and Test Instructions

**C850-0815XS (replaces W4013200 foot pedal)
for Thermal Arc 186 or ESAB ET 186i AC/DC**

  <p>SWITCH #1</p> <p>SWITCH #2</p> <p>WIRING DIAGRAM THERMAL ARC W4013200</p> <p>PLUG (END VIEW)</p>	<p>How to check the potentiometer:</p> <p>Using a multimeter on the Ohms setting, check pins 5, 6, and 7 at the end of the plug (with the pedal unplugged). The results should be as follows, with a smooth change in output as the pedal is pressed.</p> <p>NOTE: You must also press down the pedal slightly to activate the switches (but not far enough to move the potentiometer) in order to get the correct readings for the "pedal up" position.</p> <p><u>With pedal up:</u> pins 5-7 (blue-brown) = 5000 ohms pins 6-7 (red-brown) = near zero</p> <p><u>With pedal down:</u> pins 5-7 (blue-brown) = near zero pins 6-7 (red-brown) = 5000 ohms</p> <p><u>Note:</u> Resistance tolerance is $\pm 10\%$ (any value within 10% is acceptable).</p> <p>How to check switch #1:</p> <p>Use the multimeter's continuity (beep test) setting to check pins 2 and 3. It should show continuity (connection) when the pedal is pressed and turn off when released. This is what energizes the torch and activates the gas flow when it is pressed.</p>
--	---

The SSC Controls Company
8909 East Avenue Mentor, Ohio 44060
Phone: 440 205-1600 Fax: 440 205-1700