Issue 1

TM875SN   Mercedes E Class Estate (W211) 2003-2010

Item	Qty	Description	Item	Qty	Description
A	1	Crossmember	F	2	M12 x 110 Grade 10.9 Bolts & Nyloc Nuts
B	1	ACS4 / 9204 Swan Neck	G	8	M12 x 50 Bolts, Nuts & S/P Washers
C	1	L/H Side Arm	H	4	M12 x 40 Bolts & S/P Washers
D	1	R/H Side Arm	J	2	15mm Spacer Plates
E	1	Bumper Support Bracket	K	2	M8 x 20 Bolts, Nuts & S/P Washers
			L	12	12 x 40 Flat Washers
			M	12	12 x 25 Flat Washers
			N	2	8 x 20 Flat Washers
			P	1	VASP8 L/H Socket Plate

IMPORTANT: IT IS ADVISABLE TO USE A SEALANT ON MATING FACES, AND AROUND ANY MOUNTING POINTS ON REAR PANEL TO PREVENT ANY WATER DAMAGE TO CHASSIS OR BOOT.

1. Remove the rear bumper. Two fixings along rear panel, two fixings behind the boot side panel along the bumper edge, one tip screw and one push in clip on each wheel arch, four fixings along the rear panel and two along the lower edge.
2. Remove bumper beam (This is not refitted with the towbar).
3. Temporarily release the battery and jack mounting bracket to gain access to the towbar mounting holes.
4. Locate item **C** and item **D** into each chassis and using item **H** with item **L** loosely bolt to existing holes.
5. Using item **G** with item **L** and item **M** loosely bolt item **A** through the side arms and rear panel. Note; it is advisable to use a sealant to prevent any water leaking into chassis or boot.
6. Using item **K** with item **N** loosely bolt item **E** to item **A.** (Adjust to suit bumper alignment).
7. Using item **F** with item **M** and item **J** bolt item **B** and item **P** to item **A**.
8. Fully tighten all nuts and bolts and ensure the towbar is rigid and secure.
9. Refit the bumper. (If required adjust bumper bracket (item **E**) to give maximum support).

TM875SN

CHECK AND ADJUST DISTANCE BETWEEN LOWER EDGE OF TAILGATE RUBBER AND BUMPER SUPPORT BRACKET

Note:
1. Recommended Torque Setting for M12 Grade 10.9 -139 Nm. (For other Torque Settings see notes overleaf.)
2. Nose load limits and vehicle manufacturers' trailer / caravan weight limits must be observed.