

YAMAHA XP500 Tmax EFI 2007

Parts list for MCS 4380

<u>Item</u>	<u>Qty</u>	<u>Part Number</u>	<u>Description</u>
1	1	MCSU 400C	Computer
2	2		Foam mounting tape – 8cm long
3	4		M4 x 10 pan head screw
4	8		4mm flat washer
5	4		M4 Nyloc nut
		<u>MCS 4382</u>	<u>Vacuum actuator assembly</u>
6	1	MCS 574	Vacuum actuator
7	1	MCS 020B	Actuator bracket
	3		6 gauge x 3/8 pan head self tap screw
8	2	W500	M6 x 16 plated bolt and washer
9	2		6mm flat washer
10	2		M6 Nyloc nut
11	4		Foam mounting tape – 8cm long
		<u>MCS 4387</u>	<u>Vacuum hose assembly</u>
			4mm vacuum hose
12	1	MCS 031	Vacuum ‘T’ connector
13	2	MCS 032	Vacuum stop valve
		<u>MCS 4384</u>	<u>Switch assembly</u>
14	1	MCS 820	Switch
15	1	MCS 830N	Switch bracket
	4		4 gauge x 1/2” pan head self tap screw
	1		100mm cable tie
16	1	MCS 4381	Wiring loom
a			Computer plug (26 pin)
b			Fuse holder (3 amp fuse)
c			Speed sensor connectors (co-axial wire)
d			Actuator plug (4 pin)
e			Power & brake sensor wires (orange and grey wires)
f			Ground connector (black wire)
g			Control switch plug (6 pin)
		<u>MCS 4385</u>	<u>Cable Interface Unit (CIU) assembly</u>
17			
18	1	MCS 4385A	CIU housing
19	1	MCS 003F	Actuator spool
20	1	MCS 4386	Dual spool
21	1	MCS 003H	Bush
22	1	MCS 003K	End Cap
23	1		Pivot bolt M5 x 45 plated bolt
24	1		Pivot nut M5 Nyloc nut
25	2		5mm plated flat washer
26	1		M4 x 10 pan head screw (actuator cable retainer)
27	1	MCS 4385B	Mount bracket
28	1		M6 x 16 bolt

29	1		6mm flat washer
30	1	MCS 300	Carburettor cable
	15		150mm cable ties
	10		200mm cable ties
	6		300mm cable ties

Information, Set up and Operation Manual
 Operation and User Manual
 Installation Manual
 Trouble shooting guide

Parts list drawing

