







































- 1. Connect the power cord then turn the machine on WHILE PRESSING THE "CROSS" KEY.
- 2. The screen will display "POS AD xx>x"
- 3. The value of xx must be between 26 and 30. If it is not, turn the Allen screw shown in picture 19 slightly clockwise then turn the machine off and then on again (while pressing "CROSS").
- 4. Keep adjusting the allen screw until the value of xx is between 26 and 30.
- 5. You can now proceed to picture 20 and close the machine.
- 6. The machine should now be calibrated by following the steps shown in the owner's manual.