



April 15, 2009
No. 26

TECHNICAL BULLETIN

Description: XTX Ratchet Feature

Product Effected: XTX 200 Tungsten, XTX 200, XTX 100, XTX 50


Serial # Effected: 9050001 and Onward

Dear Customer,

We write to inform you of a recent decision to remove the ratchet feature from all XTX regulator venturi levers. This decision has been made due to consumer preference and to aid the manufacturing process. This will not affect the performance of the XTX regulator.

This has been achieved by removing the two ratchet inserts, in the 2nd stage case.

Regulator models which are affected are the XTX200 Tungsten, XTX200, XTX100 and the XTX50. The serial numbers of the new non-ratchet models are 9050001 and onwards. All regulators prior to this serial number will have the ratchet feature assembled as normal. There is no need to remove any ratchet inserts from in service regulators, as there are no technical issues. All XTX regulator maintenance manuals will remain unchanged showing the picture of the ratchet inserts fitted.



**Should you have any questions regarding this,
please contact Aqua Lung Customer Service at:
(877) 253-DIVE or (760) 597-5000**