

# Aqua Lung America **TECHNICAL BULLETIN**

Jan 31, 2010  
No. 30

**SUBJECT: POWERLINE GRAY BUTTON COVER (PN 15100)**

**PRODUCTS AFFECTED:**

**42746 POWERLINE INFLATOR, COMPLETE**

**42747 POWERLINE INFLATOR, LOWER UNIT**

Dear Aqua Lung Dealer,

Aqua Lung is aware that some of the **Gray** Powerline Inflator buttons are not as durable as we had anticipated. Some buttons show aging, discoloration and lack of resiliency (they remain compressed).


To improve this situation, Aqua Lung has made a material change to the button which will provide better performance and longevity. The image below helps you to identify an older button from the improved button.

The improved button has been used in our BC production since last summer. In addition, our entire inventory uses the improved button.

In an effort to upgrade the buttons in the field, Aqua Lung will be including the improved button in each of the Powerline service kits, p/n 42609, at no additional charge, for a period of one year. When servicing a Powerline inflator, please take the time to swap out an older button for an improved one.

We also encourage you to change out the buttons in your rental department.

Should you need some of the new buttons, please call our Customer Service Department at 877-253-3483 (DIVE) and they would be happy to assist you.



**Should you have any questions regarding this issue,  
please contact our customer service department at:  
(877) 253-DIVE**