


For SP Connect mirco stem mount alu Part number #53122 follow instructions 1 - 16

For SP Connect anti vibration module Part number #53135 follow instructions 17 - 31






















С























H















































































HH











































It is recommended that periodic inspections are made to ensure that all bolts are tightend to the specified torque settings.

Should the bike be involved in an accident a thorough inspection should be made and any components that have taken an impact, no matter how small, be replaced

