

Crag name	Route no.	Route name	Bolting or Rebolting	Height	No of bolts Before / After	No. Of Bolt Used	Bolt Maker/ size / model	Drill bit size	Anchor Type	Bolt type	Chemical	Name bolter/Rebolter	Bolting/rebolting date	Comment	Has the old hardware been removed (Khao Yoi)
Lopburi - Temple		Corcovado (MP)	All anchors are rebolted			17			Quick link and chain extension	SS316 glue in	Hilti 500	Cheang Qing Xin (QX) / Tao Techakanon	13/1/18		
Lopburi - Temple		Waltz With The Lovely Lady (MP) Pt. 2	Updated anchors on pitch 2			2				SS316 glue in	Hilti 500	Cheang Qing Xin (QX) / Tao Techakanon	13/1/18		
Lopburi - Temple		Pratimakam	Replaced 2 lead bolts and added 1 bolt to anchor		8	3			Quick link and chain extension	SS316 glue in	Hilti 500	Cheang Qing Xin (QX) / Tao Techakanon	28/1/18		
Lopburi - Temple		Pete's Retreat	All bolts + anchors are rebolted			7			Quick link and chain extension	SS316 glue in	Hilti 500	Cheang Qing Xin (QX) / Tao Techakanon	28/1/18		
Lopburi - Temple		Left Wings Lesbians	Anchors are rebolted			2				SS316 glue in	Hilti 500	Cheang Qing Xin (QX) / Tao Techakanon	28/1/18		
Lopburi - Temple		8C+	All bolts + anchors are rebolted			8				SS316 glue in	Hilti 500	Cheang Qing Xin (QX) / Tao Techakanon	28/1/18		
Lopburi - Temple		Nok Khao	All anchors are rebolted			9	Ti U-Bolt		2 Ti U-bolt	Titanium	Hilti 500	Cheang Qing Xin (QX) / Tao Techakanon	3/1/19	The belay of 2nd pitch is shifted 3 meters down to a ledge instead of hanging belay.	
Khao Yoi	25	Jae Contact (6b)	Anchors are rebolt, all bolts except the begining 2nd and 3rd bolts		10 / 9	7			1 ring-Titanium Climbing Anchor set with 1 link	1st shared bolt is Tortuga rest rebolted with Eterna	Hilti 500	Cheang Qing Xin (QX)	6-7/2/18		yes
Khao Yoi	26	For Us (6a+)	Anchors are rebolt, all bolts except the 3rd, 8th bolt are Fixe SS bolts		12/10	8			2 rings - Titanium Climbing Anchor set	1st bolt shares with Jae Contact. 1st, 2nd bolts are Tortuga and rest are rebolted with Eterna	Hilti 500	Cheang Qing Xin (QX)	6-7/2/18		yes
Khao Yoi	29	Made in japan (6c)	Anchors & all bolts are rebolt,		10/10	11 (additional bolt to the anchor)			1 ring-Titanium Climbing Anchor set with long & short links	1st bolt is Tortuga rest rebolted with Eterna	Hilti 500	Cheang Qing Xin (QX)	6-7/2/18		yes
Khao Yoi	32	L'herbe Rouge (6b+)	Anchors & all bolts are rebolt,		8/8	5			Share the same last part 3 bolts and with route 29	1st - 5th bolts Tortuga and the rest share with Made in Japan	Hilti 500	Cheang Qing Xin (QX)	6-7/2/18	This route needs one more bolt. Currently PG13 due to run out. - Tao-	yes
Khao Yoi	14	Chinese New year aka 2 fingers (6a+)	Anchors and all lead bolts have been replaced		9/9	10		14	Ram Horns	Eterna Ti	Hilti 500	Tao Techakanon/Ya Sripai	1/22/2019	Wasp nests have been removed, although use caution when climbing	Yes
Khao Yoi	15	August Nightmare (6c) First pitch	Anchors and all lead bolts have been replaced		9/9	4		14	Ram Horns	Eterna Ti	Hilti 500	Tao Techakanon/Ya Sripai	1/22/2019	Wasp nests have been removed. Use Caution when climbing. The first 3 bolts and the anchors are	Yes
Khao Yoi	8	No name (5)	Anchors and all lead bolts have been replaced		2bolt + 1 thread / 3 bolts	3		14	Ram Horns	Eterna Ti	Hilti 500	Snook Chaipornvadee / Erich Freeman	1/22/2019		Yes
Khao Yoi	3	No name (7b/7c)	Anchors and all lead bolts have been replaced		5/5	5		14	Ram Horns	Eterna Ti	Hilti 500	Fai, Tom, Qx	1/23/2019		
Khao Yoi	4	Magic Corner (6c)	Anchors and all lead bolts have been replaced		5/5	5		14	Ram Horns	Eterna Ti	Hilti 500	Fai, Tom, Qx	1/24/2019		
Khao Yoi	6	No name (6b)	Anchors and all lead bolts have been replaced		6/8	8		14	Ram Horns	Eterna Ti	Hilti 500	Fai, Tom, Qx	1/25/2019		
Khao Yoi	7	White Road (6b)	Anchors and all lead bolts have been replaced		8/10	10		14	Ram Horns	Eterna Ti	Hilti 500	Fai, Tom, Qx	1/26/2019		
Khao Yoi	10	Hors D'œuvre (6b)	Anchors and all lead bolts have been replaced		8 / 9	9		14	Ram Horns	Eterna Ti	Hilti 500	Pleum Chenaphun / Marco Cristell	1/30/2019	1 bolt was added by Tao on 2/3/2019	
Khao Yoi	11	Main Course (6a+)	All lead bolts have been replaced		5/6	8		14	Ram Horns	Eterna Ti	Hilti 500	Pleum Chenaphun / Marco Cristell	1/30/2019		
Khao Yoi	9	Jessica (6a+)	Anchors and all lead bolts have been replaced		8/8	8		14	Ram Horns	Eterna Ti	Hilti 500	Fai, Tao, and Kiran	2/3/2019		Yes
Khao Yoi	12	Fly by Night (6a+)	Some Lead bolts have been replaced		10/10	6		14	Ram Horns	Eterna Ti	Hilti 500	Tao and Kiran	2/3/2019	Shared anchor with Main Course. The last 3 bolts were not replaced	Yes
Khao Yoi	13	Mr. Crinkle (6b)	Anchors and all lead bolts have been replaced		11/11	10		14	Ram Horns	Eterna Ti	Hilti 500	Tao and Kiran	2/3/2019	The first bolt was not replaced	Yes
Khao Yoi	5	Simon Mark (6b+)	All lead bolts have been replaced		7/7			14	Ram Horns	Eterna Ti	Hilti 500	Tao and Kiran	2/3/2019	We only counted 7 bolts. Not 8. (perhaps gудiebook error). The anchor is shared with Route no. 6	
Khao Yoi	21	Tomahawk (7b+)	All lead bolts have been replaced		14/15	15	15 bolts for both 21 + 22	14	Ram Horns	Eterna Ti	Hilti 500	Pleum Chenaphun / Marco Cristell	2/6/2019		

Crag name	Route no.	Route name	Bolting or Rebolting	Height	No of bolts Before / After	No. Of Bolt Used	Bolt Maker/ size / model	Drill bit size	Anchor Type	Bolt type	Chemical	Name bolter/Rebolter	Bolting/rebolting date	Comment	Has the old hardware been removed (Khao Yoi)
Khao Yoi	20	For Children (5)	All lead bolts have been replaced		3/3			14	Ram Horns	Eterna Ti	Hilti 500	Pleum Chenaphun / Marco Cristell	2/6/2019		
Khao Yoi		Remember King	All lead bolts have been replaced		8/10	10		14	Stainless Steel Glue-ins by Richard Eden in 2016	Eterna TI	Hilti 500	Tao, Ya, and Kong	2/9/2019	2 Lead bolts have been added to reduce run out. Anchor was not replaced as there is Owl nesting directly above.	Yes
Khao Yoi		Three Dimension (5C)	The anchors have been replaced			2		14	Ram Horns	Eterna Ti	Hilti 500	Tao and Ha Nguyen	3/10/2019	The Lead bolts were all replaced with stainless Steel glue-ins by Richard Eden and deemed in acceptable condition	
Khao Yoi		Countdown (7A)	The Anchors have been replaced			2		14	Ram Horns	Eterna Ti	Hilti 500	Ya Sripai	3/10/2019	The Lead bolts were all replaced with Stainless Steel Glue ins by Richard Eden and deemed in acceptable condition	