


® Chester, Ct. 06412-0684 Tel: 860-526-9504

www.whelen.com

HD. T3 90 Installation and Cable Package:

- (1) 90' 50635 Cable, both ends with Sockets 61117-1 mounted & (2) Connectors 1-480303-0 installed.
- (4) Spare sockets & (1) spare Connector 1-480303-0.
- (12) Pins 61118-1 & (3) Connectors 1-480305-0 in Small Bag for Field Installation.
- (1) A421 & (1) A421-1 Pilot's Warning Placards.
- (1) A438 Lens Masking Strip.
- (1) A445 Switch Label.

To view information about our Products. Installation Guides. Installation and Service Manual, Trouble Shooting Procedure for Strobe Light Systems, Technical Support, System Recommendations, PMA Supplements, STC's and illustrated Spare Parts Catalog visit www.whelen.com or contact our aviation sales dept. at (860) 526-9504.




©1998 Whelen Engineering Company. Form No.13296B (062810)

® Chester, Ct. 06412-0684 Tel: 860-526-9504 www.whelen.com

HD. T3 90 Installation and Cable Package:

- (1) 90' 50635 Cable, both ends with Sockets 61117-1 mounted & (2) Connectors 1-480303-0 installed.
- (4) Spare sockets & (1) spare Connector 1-480303-0.
- (12) Pins 61118-1 & (3) Connectors 1-480305-0 in Small Bag for Field Installation.
- (1) A421 & (1) A421-1 Pilot's Warning Placards.
- (1) A438 Lens Masking Strip.
- (1) A445 Switch Label.

To view information about our Products. Installation Guides Installation and Service Manual, Trouble Shooting Procedure for Strobe Light Systems, Technical Support, System Recommendations, PMA Supplements, STC's and illustrated Spare Parts Catalog visit www.whelen.com or contact our aviation sales dept. at (860) 526-9504.




©1998 Whelen Engineering Company, Form No.13296B (062810)

® Chester, Ct. 06412-0684 Tel: 860-526-9504 www.whelen.com

HD. T3 90 Installation and Cable Package:

- (1) 90' 50635 Cable, both ends with Sockets 61117-1 mounted & (2) Connectors 1-480303-0 installed.
- (4) Spare sockets & (1) spare Connector 1-480303-0.
- (12) Pins 61118-1 & (3) Connectors 1-480305-0 in Small Bag for Field Installation.
- (1) A421 & (1) A421-1 Pilot's Warning Placards.
- (1) A438 Lens Masking Strip.
- (1) A445 Switch Label.

To view information about our Products. Installation Guides. Installation and Service Manual, Trouble Shooting Procedure for Strobe Light Systems, Technical Support, System Recommendations, PMA Supplements, STC's and illustrated Spare Parts Catalog visit www.whelen.com or contact our aviation sales dept. at (860) 526-9504.




©1998 Whelen Engineering Company, Form No.13296B (062810)

® Chester, Ct. 06412-0684 Tel: 860-526-9504 www.whelen.com

HD, T3 90 Installation and Cable Package:

- (1) 90' 50635 Cable, both ends with Sockets 61117-1 mounted & (2) Connectors 1-480303-0 installed.
- (4) Spare sockets & (1) spare Connector 1-480303-0.
- (12) Pins 61118-1 & (3) Connectors 1-480305-0 in Small Bag for Field Installation.
- (1) A421 & (1) A421-1 Pilot's Warning Placards.
- (1) A438 Lens Masking Strip.
- (1) A445 Switch Label.

To view information about our Products, Installation Guides, Installation and Service Manual. Trouble Shooting Procedure for Strobe Light Systems, Technical Support, System Recommendations, PMA Supplements, STC's and illustrated Spare Parts Catalog visit www.whelen.com or contact our aviation sales dept. at (860) 526-9504.



® Chester, Ct. 06412-0684 Tel: 860-526-9504 www.whelen.com


HD, T3 90 Installation and Cable Package:

- (1) 90' 50635 Cable, both ends with Sockets 61117-1 mounted & (2) Connectors 1-480303-0 installed.
- (4) Spare sockets & (1) spare Connector 1-480303-0.
- (12) Pins 61118-1 & (3) Connectors 1-480305-0 in Small Bag for Field Installation.
- (1) A421 & (1) A421-1 Pilot's Warning Placards.

©1998 Whelen Engineering Company. Form No.13296B (062810)

- (1) A438 Lens Masking Strip.
- (1) A445 Switch Label.

To view information about our Products, Installation Guides, Installation and Service Manual. Trouble Shooting Procedure for Strobe Light Systems, Technical Support, System Recommendations, PMA Supplements, STC's and illustrated Spare Parts Catalog visit www.whelen.com or contact our aviation sales dept. at (860) 526-9504.



CAUTION: Cables connecting remote power supply type strobe lights must be connected correctly!

® Chester, Ct. 06412-0684 Tel: 860-526-9504 www.whelen.com

HD, T3 90 Installation and Cable Package:

- (1) 90' 50635 Cable, both ends with Sockets 61117-1 mounted & (2) Connectors 1-480303-0 installed.
- (4) Spare sockets & (1) spare Connector 1-480303-0.
- (12) Pins 61118-1 & (3) Connectors 1-480305-0 in Small Bag for Field Installation.
- (1) A421 & (1) A421-1 Pilot's Warning Placards.
- (1) A438 Lens Masking Strip.
- (1) A445 Switch Label.

To view information about our Products. Installation Guides. Installation and Service Manual. Trouble Shooting Procedure for Strobe Light Systems, Technical Support, System Recommendations, PMA Supplements, STC's and illustrated Spare Parts Catalog visit www.whelen.com or contact our aviation sales dept. at (860) 526-9504.



CAUTION: Cables connecting remote power supply type strobe lights must be connected correctly!

©1998 Whelen Engineering Company. Form No.13296B (062810)