

Fitting Instructions for the Landcruiser 300 Series (All Models) Centre Console Cover

Fitting Instructions - A step by step guide

Step 1) From the drivers side lift the console slightly by pressing the button



Step 2) With the console raised slightly on the drivers side (as per step 1) press the passengers side button and lift the back of the console up.



This will allow the arm at the back of the console to come away and allow you to fit the console in later steps (see pic below)



If the arm at the back has not come away correctly it will still be locked in place and look like this. If it still looks like this, repeats steps 1 and 2.



Step 3) Fit the 3 corners first. At this stage you won't be able to fit the front passengers side section.



Once all 3 sides have been tucked under correctly lower the console on the drivers side. It may take a little bit of force to flatten it down at this point. **If it won't close** it means you have fitted it incorrectly and the material is interfering. Please lift the console and have a look. It's likely that you have pulled down a section too far downwards – either in the corner or on the side which is creating an obstruction on closure.



Step 4) Once closed on the drivers side, lift the passengers side latch so you can then fit the front passengers side section. And then close.

If fitted correctly it should look like the below photos. Please Note: This has been one of the toughest console covers to design based on the size of the console, but mainly due to the sideways opening (different to the conventional front opening console). We have come up with a console cover which will open and close, however it may take a bit of force initially to close the console. After a few weeks it will compress and become easier to close. In the event that it is not closing (even with a bit of force) then it is a fitment error and something is obstructing it underneath – We go into more detail below.







IF THE CONSOLE COVER IS NOT CLOSING – Please lift the console and have a look. It's likely that you have pulled down a section too far downwards – either in the corner or on the side which is creating an obstruction on closure.

