

HONDA XL1000V Varadero from 2003

Parts list for MCS 6400 kit (without ABS brakes)

<u>Item</u>	<u>Qty</u>	<u>Part Number</u>	<u>Description</u>
1	1	MCS 8000C	Computer
2	2 lengths		Self-adhesive Velcro tape (2 x 8cm pieces)
		<u>MCS 6402</u>	<u>Electric Throttle Servo assembly</u>
3	1	MCS 850	Electric Throttle Servo
4	1	MCS 850C	Servo nose
5	3		M4 x 12 pan head screws
6	1		3/4" x 3/32" (19 x 3mm) 'O' ring
7	1	MCS 850B	Cable sealing boot
8	2	MCS 054	Wire ring cable retainer (1 spare)
9	1	MCS 6402A	Servo mounting tabs
10	2	HoseClamp24	Hose clamp 27~51mm
11	1	MCSSC 750	Throttle servo cable - no ABS
12	1	<u>MCS 6401</u>	<u>Wiring harness</u>
a			Computer plug (26 pin)
b			Fuse holder (3 amp fuse)
c			Tach sensor (yellow wire)
d			Speed sensor (co-axial wire)
e			Throttle Servo plug (4 pin)
f			Power & brake sensor (orange and grey wires)
g			Ground connector (black wire)
h			Neutral sensor (blue wire)
i			Control switch plug (6 pin)
		<u>MCS 4544</u>	<u>Control Switch assembly</u>
13	1	MCS 820	Control Switch
14	1	MCS 830L	Switch bracket
	4		4 gauge x 1/2" pan head self-tap screw
15		<u>MCS 6405</u>	<u>Cable Interface Unit (CIU) assembly (no ABS)</u>
16	1	MCS 6405A	CIU housing
17	1	MCS 003F	Actuator spool
18	1	MCS 6406	Dual spool
19	1	MCS 003H	Bush
20	1	MCS 003K	End Cap
21	1		M5 x 45 pivot bolt
22	1		Pivot nut M5 Nylok nut
23	2		5mm plated flat washer
24	1		M4 x 10 pan head screw (actuator cable retainer)
25	1	MCS 4545B	CIU mounting bracket
26	2	HoseClamp6	Hose clamp 8~22mm
27	1	MCSCC 250	Carburettor cable (no ABS)
	10		100mm cable ties
	10		150mm cable ties
	6		300mm cable ties
	1 bottle		Throttle cable oil (Singer industrial sewing machine oil)

Information, Set up and Operation Manual
Operation and User Manual
Installation Manual
Trouble shooting guide

