

HEIGH10 (UN1810) System Firmware Update

Accessing the Installer Settings



1. From any source, press the HOME Button



2. From the HOME MENU select Settings



3. Select System Settings



4. Select Installer Settings > Enter



5. Enter Passcode 0052 > OK



Checking System Firmware Version

Checking and updating the System Firmware and PAC Integration APK is an important step for proper operation. This should be done first before setting any system and vehicle settings as those settings may be lost after an update.

5	SETTINGS	X
Installer Settings	A	
FM Tuning Steps		100KH 200KH
System Information		Þ
Advanced Vehicle Cett	in	
Advanced Vehicle Set	lings	
System Update		Update
PAC Update		Update
Factory Reset		Reset

1. Access the Installer Settings (Page: 2) and select **System Information** to view firmware information.



2. The third line shows the APP Version. Note the APP Version and head over to the UN1810 product page on stingerelectronics.com. Select the Firmware Tab on the product page. The most current firmware will be listed. The last 8 digits of the APP Version is the firmware version date code (YYYYM-MDD). If the date code of the installed firmware is older than the current firmware on the website, proceed to Updating System Firmware.



Updating System Firmware

1. Format a USB Drive


Before copying the firmware file to a USB Flash Drive, the USB drive will need to be formatted to FAT32 / MS-DOS(FAT)

USB Drive Format: Windows PC


A. Insert a 4GB+ USB Drive

B. Open File Explorer

C. Right click on USB Drive & select Format



D. Select FAT 32 File System and uncheck Quick Format and click Start.



USB Drive Format: Mac

A. Insert a 4GB+ USB Drive


B. Launch the Disk Utility App from the Utilities folder



C. Select the USB drive from the "External" List and click Erase



D. Select MS-DOS(FAT) from the format drop-down menu and click Erase





Updating System Firmware (cont.)

2. Download Firmware & Transfer To USB Drive

Download the firmware file from StingerElectronics.com. Transfer the firmware file "as is" onto the formatted USB drive. The file must be in the root directory of the USB drive. **Do not unzip the file.** See example A for Windows and B for Mac.

A. Windows PC

This DC	^ Name	^	Date modified
I This PC J 3D Objects	SWUN1	810_Stinger_09-27-2020_10C	9/26/2020 9:55 PM
Desktop			
Documents			
Downloads			
Music			
Pictures			
🖥 Videos			
S (C:)			
USB Drive (D:)			

B. Mac



NOTE: If Safari is automatically unzipping the file after downloading: 1. Open Safari. 2. Click Preferences. 3. Under the General tab, uncheck the option Open "safe" files after downloading. 4. Download the file again.

3. Install System Update

Insert the USB drive into either USB port on the radio.

NOTE: When updating the firmware, all settings will be reset to factory defaults.... station presets, EQ presets, audio/crossover settings, time alignment, camera settings. If need be, record this information before updating firmware.

5	SETTINGS		Х
Installer Settings	A		
FM Tuning Steps		100KH	200KH
System Information			٢
Advanced Vehicle Set	tings		۲
System Update			Update
PAC Update			Update
Factory Reset			Reset

A. Access the Installer Settings (Page: 1) and select **System Update**

The update will take 6-8 minutes.

Do not attempt to stop the update. DO NOT turn off power. The system will be damaged if power is lost during the update process.



Updating System Firmware (cont.)

4. System Update Installation Complete

When the system update is complete, the Radio source will be displayed. If you don't see the Radio screen shown below, DO NOT turn off power!



5. Confirm Update and Perform Factory Reset

For the new firmware to perform as intended, a Factory Reset needs to be performed.



1. From the Radio source, press the HOME Button




2. From the HOME MENU select Settings



Confirm Update (cont.)



3. Select System Settings



4. Select Installer Settings > Enter



5. Enter Passcode 0052 > OK



7. Confirm the App Version has been updated.



6. Select System Information



8. Press the Back Arrow to return to the Installer Settings.



Factory Reset

📁 💷 iPhone X SETTINGS		Х
Installer Settings		
FM Tuning Steps	100KH	200KH
System Information		٢
Advanced Vehicle Settings		•
System Update		Update
PAC Update		Update
Factory Reset		Reset

9. Select Factory Reset from the Installer Settings



10. The Factory Reset will take 2-3 minutes. DO NOT turn off power during the reset.



11. When the Factory Reset is complete, the Radio source will be displayed.

Technical Support: Phone: 727-592-5991 Email: support@aampglobal.com Chat: stingerelectronics.com Stinger is a Power Brand of AAMP Global 15500 Lightwave Drive Clearwater, Florida 33760 P: 888-228-5560 | © 2020 AAMP Global