SERVICE LIFE AND TIME BETWEEN OVERHAULS

Prime Turbines, LLC FAA CRS No. 5TPR585C

| | | Part No: 1-000-060-23 | | | | Serial No: LE-10901Z | | |
|--|-----------------------|--|--------|------------|---------------------------------|--|---|--|
| TSN: | N: LCF1 (GP): 8491.44 | | | | SO: HEI: 1200 | | HEI Remain 1013.2 | |
| REF: T53 Service Bulletin SB .0020 Revision: 2 Date: 11/25/02 To be stamped after physical verification as indicated by INSPECTOR: DATE: 12/12/19 | | TBO = Time Between Overhauls TSN = Time Since New TRL = Time Retirement Life TR = Time Remaining | | | etirement Life N Remaining U | N = Serial Number IR = Not Removed INK = Unknown A = Not Applicable | noved FL = From Logbook own HEI = Hot End Inspection | |
| | | To be stamped after records review INSPECTOR: DATE: 12/11/19 | | | | To be stamped prior to installation INSPECTOR: DATE: 12/12/19 | | |
| AS REC | AS RECEIVED | | | AS SHIPPED | | | | |
| NOMENCLATURE | PN | TSN | TRL | TR | PN | TSN | TR | |
| | SN | CSN | CRL | CR | SN | CSN | CR | |
| ☐ FRONT SHAFT | 1-100-495-07 | 5191.3 | 25,000 | 19808.7 | 1-100-495-07 | 5191.3 | 19808.7 | |
| | M39196 | 6529.34 | 25,000 | 18470.66 | M39196 | 6529.34 | 4 18470.6 | |
| COMP DRUM | 1-101-250-03 | 4278.9 | 12,000 | 7721.1 | 1-101-250-03 | 4278.9 | 7721.1 | |
| | M218445 | 7167.34 | 16,500 | 9332.66 | M218445 | 7167.34 | 9332.66 | |
| POWERSHAFT | 1-100-800-04 | 6231.9 | 25,000 | 18768.1 | 1-100-800-04 | 6231.9 | 18768.1 | |
| | 6030 | 5831.3 | 25,000 | 19168.7 | 6030 | 5831.3 | 19168.7 | |
| ☐ IMPELLER | 1-100-078-07/08 | N/A | 15,800 | N/A | 1-100-078-07/0 | 8 N/A | N/A | |
| | N/A | N/A | 5,000 | N/A | N/A | N/A | N/A | |
| ☐ IMPELLER | 1-100-078-13 | 2316.1 | 15,800 | 13483.9 | 1-100-078-13 | 2316.1 | 13483.9 | |
| | 061335107311 | 3627.34 | 14,000 | 10372.66 | 061335107311 | 3627.34 | 4 10372.6 | |
| | | | | | | | | |

Form: PTPHX-GF-2077M IR (12/03/2014)

Page 1 of 3

W/O: M1R1088