


Tech Brief DSP8.8 SW/FM/APP Update FIRMWARE 1.2.7

Current users who choose to or are required to update their DSP8.8 Software, Firmware & Apps





 $\label{lem:products} Firmware, PC\ Application, Set\ Up\ Tracks,\ User\ Guide\ -\ Available\ @\ https://phoenixgold.com/catalog/all-products/digital-signal-processor$

Users performing field updates to Version or customers who receive new units from 1.2.7 forward must update all devices associated with their DSP8.8.

This includes all PC, MAC Tablets and Phones to the versions posted below

Customers using windows 10 machines to update the DSP8.8 to Firmware version 1.2.7 must confirm their windows version 17.03 / 17.09 X64 or higher.

All units shipping from todays date and beyond will be pre loaded with the 1.2.7 firmware or higher.

These units will no longer function with pre- 1.3 version applications.

Users who choose to have automatic updates on their selected apps may lose the ability to control their DSP.
Updating the DSP8.8's firmware will be required for continued use.

Firmware Updates Include

Added new audio signal configurations for RCA and Hi-Level inputs for easier system setup.

Added new visual indicators for each EQ band that is adjusted beyond flat for easier system tuning.

Added new identification rings for Inputs, Channels and Presets when selected for easier system control & setup.

Fixed bugs on Preset Copy and Preset Title to prevent DSP from unexpected rebooting.

Confirm customer is using version 1.3 or higher on their preferred app











Tech Support: 800-477-2267





