## Tungsten & Tool Ltd 🖸

## CNC MAINTENANCE GUIDELINE

- CLEANLINESS
- FILTERS
- LUBRICATION
- AIR SUPPLY
- POWER



There is no standardised schedule but all filters should be checked weekly and changed as needed.



CNC routers don't require extensive lubrication but bearings and pumps do need regular lubrication. Anyway maintenance schedules vary.





The pneumatic air your CNC machine needs has to be clean, dry and maintained at a steady pressure greater than 552 kPa (80 psi).



Always follow local power regulations!

Poor electrical grounding and low
voltage or insufficient capacity
can cause massive failure.

