

*
* ee203 BOOTLOADER
*

ee203-bl-20181210-A

Fixes bug which would cause [C]alibration command to crash on units sold after December 2018.

ee203-bl-20151006-A

Dismount EE203 flash drive when the application launches.

ee203-bl-20150915-A

Increased USB CDC max packet size to improve serial performance.
Reload volume directory after loading a new firmware image.

ee203-bl-20150621-C

Initial production release.

*
* ee203 APPLICATION
*

ee203-app-20151008-A

requires: ee203-bl-20151006-A or ee203-bl-20181210-A
Remove NUL byte sent at the end of some strings.
Add [V]ersion command.

ee203-app-20150915-A

requires: ee203-bl-20150915-A
Modified calibration algorithm to saturate rather than discard out-of-range samples.
Modified range switching algorithm to minimize glitching on LO to HI range switch.

ee203-app-20150728-A

requires: ee203-bl-20150621-C
Improved calibration algorithm to make calibration constants more stable.
Suppressed task overflow check on startup.
Fixed text error on 'S' command.

ee203-app-20150621-A

requires: ee203-bl-20150621-C
Initial production release.