



Snap ring groove cutting print and information:

Snap ring grooves must be machined as noted.
Axle length may be shortened.

To cut grooves, use proper width cutting tool on a lathe and cut splines slowly (~100 RPM) to avoid chatter due to high hardness. The axle length may be reduced in the sam fashion.

