JESMON[®] TE[®]

MATERIAL SAFETY DATA SHEET: RELEASE AGENT

1. IDENTIFIC	CATION OF THE SUBSTANCE / P	REPARATION AND THE COMPANY	
Product nan	ne		
JESMONITE	APW RELEASE AGENT		
Application of Product:			
Release Agent.			
Company Ac	ldress:		
Jesmonite Li	mited. Challenge Court, Bishop's	Castle, Shropshire, SY9 5DW	
Information	in case of emergency:		
Tel:+44 (0) 1588 630302 Fax:+44 (0) 1588 630304 Web: www.jesmonite.co.uk Email: sales@jesmonite.co.uk			
2. COMPOSITION / INFORMATION ON INGREDIENTS			
	mposition: Mineral oil and solver DENTIFICATION	nt naptha. N-Octadeclamin.	
No specific	hazard.		
4. FIRST AID	MEASURES		
In all cases o	f doubt seek medical attention.		
Skin:	Wash thoroughly with soap and w	vater.	
Eyes:	Irrigate for at least 15 minutes wit	th water.	
Inhalation:	Remove to fresh air.		
Ingestion:	Do not induce vomiting. See mee	dical attention.	
	ITING MEASURES		
-	ng media: Sand, foam, Co2, dry p		
Special exposure: Combustion may release black smoke.			
	quipment: Self-contained breathir	ng mask.	
	TAL RELEASE MEASURES		
	otection: Avoid contact with skin a		
Environmental: Remove and cover with dry sand, absorbent material. 7. HANDLING AND STORAGE			
		n and eyes. Do not breathe vapour.	
Storage: Keep container closed and store in a cool, dry place.			
	RE CONTROLS / PERSONAL PRO		
	RE CONTROLS / PERSONAL PRO control measures: Ensure adec		
	control measures: Ensure adec		
Engineering	control measures: Ensure adec		
Engineering Personal pro	control measures: Ensure adec	quate ventilation.	
Engineering Personal pro Respiratory:	control measures: Ensure adec	uate ventilation. Ensure adequate ventilation	
Engineering Personal pro Respiratory: Hands:	control measures: Ensure adec	quate ventilation. Ensure adequate ventilation Wear gloves	
Engineering Personal pro Respiratory: Hands: Eyes: Skin: Industrial hy	control measures: Ensure adec otection giene:	quate ventilation. Ensure adequate ventilation Wear gloves Wear safety glasses	
Engineering Personal pro Respiratory: Hands: Eyes: Skin: Industrial hy	control measures: Ensure adec	quate ventilation. Ensure adequate ventilation Wear gloves Wear safety glasses Work clothes	
Engineering Personal pro Respiratory: Hands: Eyes: Skin: Industrial hy 9. PHYSICAI Appearance	control measures: Ensure adec otection giene:	quate ventilation. Ensure adequate ventilation Wear gloves Wear safety glasses Work clothes Keep away from F.D.T. Wash hands.	
Engineering Personal pro Respiratory: Hands: Eyes: Skin: Industrial hy 9. PHYSICAI Appearance Odour	control measures: Ensure adec otection giene: - AND CHEMICAL PROPERTIES Brownish paste	quate ventilation. Ensure adequate ventilation Wear gloves Wear safety glasses Work clothes Keep away from F.D.T. Wash hands. Typical solvent	
Engineering Personal pro Respiratory: Hands: Eyes: Skin: Industrial hy 9. PHYSICAI Appearance Odour Melting poin	control measures: Ensure adec otection giene: - AND CHEMICAL PROPERTIES Brownish paste	quate ventilation. Ensure adequate ventilation Wear gloves Wear safety glasses Work clothes Keep away from F.D.T. Wash hands. Typical solvent >150℃	
Engineering Personal pro Respiratory: Hands: Eyes: Skin: Industrial hy 9. PHYSICAI Appearance Odour Melting point Flash point	control measures: Ensure adec ptection giene: - AND CHEMICAL PROPERTIES Brownish paste	quate ventilation. Ensure adequate ventilation Wear gloves Wear safety glasses Work clothes Keep away from F.D.T. Wash hands. Typical solvent >150 ℃ >24 ℃	
Engineering Personal pro Respiratory: Hands: Eyes: Skin: Industrial hy 9. PHYSICAI Appearance Odour Melting point Flash point Ignition tem	control measures: Ensure adec ptection giene: - AND CHEMICAL PROPERTIES Brownish paste tt	quate ventilation. Ensure adequate ventilation Wear gloves Wear safety glasses Work clothes Keep away from F.D.T. Wash hands. Typical solvent >150 ℃ >24 ℃ >200 ℃	
Engineering Personal pro Respiratory: Hands: Eyes: Skin: Industrial hy 9. PHYSICAI Appearance Odour Melting point Flash point Ignition tem Lower explo	control measures: Ensure adec ptection giene: - AND CHEMICAL PROPERTIES Brownish paste tt p sive limit	quate ventilation. Ensure adequate ventilation Wear gloves Wear safety glasses Work clothes Keep away from F.D.T. Wash hands. Typical solvent >150 ℃ >24 ℃ >200 ℃ 0.8 vol %	
Engineering Personal pro Respiratory: Hands: Eyes: Skin: Industrial hy 9. PHYSICAI Appearance Odour Melting point Flash point Ignition tem Lower explo Upper explo	control measures: Ensure adec ptection giene: - AND CHEMICAL PROPERTIES Brownish paste at p sive limit sive limit	quate ventilation. Ensure adequate ventilation Wear gloves Wear safety glasses Work clothes Keep away from F.D.T. Wash hands. Typical solvent >150 ℃ >24 ℃ >200 ℃	
Engineering Personal pro Respiratory: Hands: Eyes: Skin: Industrial hy 9. PHYSICAI Appearance Odour Melting point Flash point Ignition tem Lower explo Upper explo 10. STABILI	control measures: Ensure adec ptection giene: - AND CHEMICAL PROPERTIES Brownish paste t sive limit sive limit FY AND REACTIVITY	quate ventilation. Ensure adequate ventilation Wear gloves Wear safety glasses Work clothes Keep away from F.D.T. Wash hands. Typical solvent >150 ℃ >24 ℃ >200 ℃ 0.8 vol % 6.0 vol %	
Engineering Personal pro Respiratory: Hands: Eyes: Skin: Industrial hy 9. PHYSICAI Appearance Odour Melting point Flash point Ignition tem Lower explo Upper explo 10. STABILI Chemical sta	control measures: Ensure adec otection gene: - AND CHEMICAL PROPERTIES Brownish paste at p sive limit sive limit TY AND REACTIVITY ability: Chemically stable under co	quate ventilation. Ensure adequate ventilation Wear gloves Wear safety glasses Work clothes Keep away from F.D.T. Wash hands. Typical solvent >150 ℃ >24 ℃ >200 ℃ 0.8 vol % 6.0 vol % Derrect storage conditions.	
Engineering Personal pro Respiratory: Hands: Eyes: Skin: Industrial hy 9. PHYSICAI Appearance Odour Melting point Flash point Ignition tem Lower explo Upper explo 10. STABILI Chemical sta Hazardous o	control measures: Ensure adec otection /giene: AND CHEMICAL PROPERTIES Brownish paste at p sive limit sive limit IY AND REACTIVITY ability: Chemically stable under con- lecomposition: None when stored	quate ventilation. Ensure adequate ventilation Wear gloves Wear safety glasses Work clothes Keep away from F.D.T. Wash hands. Typical solvent >150 ℃ >24 ℃ >200 ℃ 0.8 vol % 6.0 vol % Derrect storage conditions.	
Engineering Personal pro Respiratory: Hands: Eyes: Skin: Industrial hy 9. PHYSICAI Appearance Odour Melting point Flash point Ignition tem Lower explo Upper explo 10. STABILI Chemical sta Hazardous of 11. TOXILOO	control measures: Ensure adec otection /giene: AND CHEMICAL PROPERTIES Brownish paste at p sive limit sive limit IY AND REACTIVITY ability: Chemically stable under co lecomposition: None when stored GICAL INFORMATION	quate ventilation. Ensure adequate ventilation Wear gloves Wear safety glasses Work clothes Keep away from F.D.T. Wash hands. Typical solvent >150 ℃ >24 ℃ >200 ℃ 0.8 vol % 6.0 vol % Derrect storage conditions. d and handled correctly.	
Engineering Personal pro Respiratory: Hands: Eyes: Skin: Industrial hy 9. PHYSICAI Appearance Odour Melting point Flash point Ignition tem Lower explo Upper explo 10. STABILI Chemical sta Hazardous of LD50 Oral - r	control measures: Ensure adec otection /giene: AND CHEMICAL PROPERTIES Brownish paste brownish paste t p sive limit sive limit IY AND REACTIVITY ability: Chemically stable under co lecomposition: None when stored GICAL INFORMATION at	quate ventilation. Ensure adequate ventilation Wear gloves Wear safety glasses Work clothes Keep away from F.D.T. Wash hands. Typical solvent >150 ℃ >24 ℃ >200 ℃ 0.8 vol % 6.0 vol % Derrect storage conditions.	
Engineering Personal pro Respiratory: Hands: Eyes: Skin: Industrial hy 9. PHYSICAI Appearance Odour Melting point Flash point Ignition tem Lower explo Upper explo 10. STABILI Chemical sta Hazardous co 11. TOXILOO LD50 Oral - r 12. ECOLOO	control measures: Ensure adec ptection giene: AND CHEMICAL PROPERTIES Brownish paste t p sive limit sive limit ry AND REACTIVITY ability: Chemically stable under co lecomposition: None when stored SICAL INFORMATION at SICAL INFORMATION	quate ventilation. Ensure adequate ventilation Wear gloves Wear safety glasses Work clothes Keep away from F.D.T. Wash hands. Typical solvent >150 ℃ >24 ℃ >200 ℃ 0.8 vol % 6.0 vol % Derrect storage conditions. d and handled correctly.	
Engineering Personal pro Respiratory: Hands: Eyes: Skin: Industrial hy 9. PHYSICAI Appearance Odour Melting point Flash point Ignition tem Lower explo Upper explo 10. STABILI Chemical sta Hazardous of 11. TOXILOO LD50 Oral - r 12. ECOLOO Do not allow	control measures: Ensure adec ptection giene: AND CHEMICAL PROPERTIES Brownish paste t p sive limit sive limit sive limit ry AND REACTIVITY ability: Chemically stable under co lecomposition: None when stored SICAL INFORMATION at SICAL INFORMATION into drains or water courses.	quate ventilation. Ensure adequate ventilation Wear gloves Wear safety glasses Work clothes Keep away from F.D.T. Wash hands. Typical solvent >150 ℃ >24 ℃ >200 ℃ 0.8 vol % 6.0 vol % Derrect storage conditions. d and handled correctly.	
Engineering Personal pro Respiratory: Hands: Eyes: Skin: Industrial hy 9. PHYSICAI Appearance Odour Melting point Flash point Ignition tem Lower explo Upper explo 10. STABILIT Chemical sta Hazardous of 11. TOXILOO LD50 Oral - r 12. ECOLOO Do not allow 13. DISPOS/	control measures: Ensure adec ptection	puate ventilation. Ensure adequate ventilation Wear gloves Wear safety glasses Work clothes Keep away from F.D.T. Wash hands. Typical solvent >150 ℃ >24 ℃ >200 ℃ 0.8 vol % 6.0 vol % Drrect storage conditions. d and handled correctly. >5000mg/kg	
Engineering Personal pro Respiratory: Hands: Eyes: Skin: Industrial hy 9. PHYSICAI Appearance Odour Melting point Flash point Ignition tem Lower explo Upper explo 10. STABILI Chemical sta Hazardous of 11. TOXILOO LD50 Oral - r 12. ECOLOO Do not allow 13. DISPOS/ May be incide	control measures: Ensure adec ptection	puate ventilation. Ensure adequate ventilation Wear gloves Wear safety glasses Work clothes Keep away from F.D.T. Wash hands. Typical solvent >150 ℃ >24 ℃ >200 ℃ 0.8 vol % 6.0 vol % Drrect storage conditions. d and handled correctly. >5000mg/kg	
Engineering Personal pro Respiratory: Hands: Eyes: Skin: Industrial hy 9. PHYSICAI Appearance Odour Melting point Flash point Ignition tem Lower explo Upper explo 10. STABILI Chemical sta Hazardous of 11. TOXILOO LD50 Oral - r 12. ECOLOO Do not allow 13. DISPOS/ May be incide	control measures: Ensure adec ptection	puate ventilation. Ensure adequate ventilation Wear gloves Wear safety glasses Work clothes Keep away from F.D.T. Wash hands. Typical solvent >150 ℃ >24 ℃ >200 ℃ 0.8 vol % 6.0 vol % Drrect storage conditions. d and handled correctly. >5000mg/kg	

Packing group	111
ICAO/IATA	4.1
Flash point	> 21 °C
IMDG/GGVSee	4.1
Ems	4.05
Marine pollutant	Yes
Name for shipment:	Solids containing flammable liquid, N.O.S., petroleum distillates.
15. REGULATORY INFORMATION	
Not classified	
16. OTHER INFORMATION	

For use by persons cognisant with the use of this material.

Disclaimer of Liability

The information in this MSDS was obtained from sources we believe are reliable. However, the information is provided without any warranty, express or implied, regarding its correctness. The conditions or methods of handling, storage, use or disposal of the product are beyond our control and may be beyond our knowledge. For this and other reasons, we do not assume responsibility and expressly disclaim liability for loss, damage or expense arising out of or in any way connected with the handling, storage, use or disposal of the product.

This MSDS was prepared and is to be used only for this product. If the product is used as a component in another product, this MSDS may not be acceptable.