## 1st STEP

METAL WALL BRACKET , LEVEL AND FIX WITH FOUR SCREWS INTO SUITABLE WALL PLUGS FLANGE ON TOP AND POINTING AWAY FROM WALL (60, 480 J60 0 50 o. 0. 295 2nd STEP FOUR MAGNETS WITH SPACERS Ö 44 BEHIND , DRILL AND PLUG WALL , FIX WITH SCREWS NOTE - THE POSITION OF THESE FOUR MAGNETS IS NOT CRITICAL IT IS +/- 10mm ( SEE DRAWING No 2 )

600mmW X 1000mmH

480

600

60

## Onglass Products Ltd Glass Boards Fitting Instructions - Drawing 1

60



