


HOW TO MEASURE SECURITY SCANNER RADIATION SHIELDS

These instructions are for machines with individual curtain flaps. If you have a full curtain set, please see instructions for measuring radiation curtains.

First remove a flap from your scanner and place on a flat surface.




1. Measure the curtain lengthwise. Ensure the hangar holes are visible when you take a picture.



2. Measure the curtain across the. Take picture with the hangar holes visible.



3. If you have a micrometer, take a measurement or the curtain thickness. This helps us confirm you have the correct radiation protection level.



4. Take a picture of the nameplate so we insure the curtains are labeled for the right unit on Packing Slip.

Please count how many worn flaps you have on the scanner so we have an accurate number for the quotation.

Please send the photos by email to: sales@leadfreeshields.com

or by text to: +1 832-519-8787

You can also take detailed measurements and send those by email.

**Order Online for
Fastest Shipment
to over 100 Countries**

Order online at www.XrayCurtains.com