1. Double-click to launch the upgrade tool.

^	名称 1	修改日期	美型	大小
	ASM3142_MPTool	2017/3/31 14:20	应用程序	1,239 K
1	ASM3142MPTool	2016/6/27 17:09	配置设置	1 K
1	Asmlo.sys	2015/2/2 13:38	系统文件	11 K
1	Asmlo64.sys	2015/2/2 16:26	系统文件	20 K
1	asmiodll.dll	2014/12/15 17:53	应用程序扩展	48 K
*	BrowsedBINPath	2021/3/23 16:58	文本文档	1 KI
	Config_170724_70_F2_20.rom	2020/7/24 15:35	ROM 文件	128 K
	Config_181004_70_02_00.rom	2021/3/19 18:11	ROM 文件	128 K
	Config_191209_70_02_40.rom	2021/2/4 10:32	ROM 文件	128 KI
	Config_191209_70_F2_18.rom	2021/3/23 16:58	ROM 文件	128 K
	devconAMD64	2010/2/9 12:56	应用程序	80 K

2. Enter unlocking password : asmedia.



3. Select the firmware file: 191209_70_F2_18.bin

AainPage Upgrade V Update En more Brown	nt C Test sble	: Usen	s\123\k	esktop)	PW (45M	3142MPTool	v1122(ASM31-	12HPTool.ini	Firmware Info	Lock M	eck Enable	Function Tes	as. 1. 2.0 3.0 ⊮ USE	13.1	
SVID IB21 F PCI SPEED Ena Max	ble]											Time Out(ms)	Signal Line Te	st	
Manual Setting		E I	Custom	ver Inform	mation ation (M4	α 31) [
Manual Setting Reg Setting	Bus	Dev 0	Custore ustomer Fun	er Infor r Inform SSID 2142	mation ation (MA SVID 1b21	(X 31) Update	US82 Port1	USB2 Port2	USB3 Port1	US83 Port2	US83.1 Port1	USB3.1 Port2	SLT Result	TT Result	LTF
Wanual Setting Reg Setting IPW Version 191200_70_F2_18	Bus	Dev 0	Custorr Istomer Fun 0	ssiD 2142	mation ation (M# SVID 1b21	(X 31) Update	US82 Porti	USB2 Port2	USB3 Port1	US83 Port2	US83.1 Port1	USB3.1Port2	SLT Result	TT Result	LT

4. Start burning the firmware, and wait for 20s.

AIPPage Upgrade Test VUpgrade Test Firmware Browser Sub_Sys SSID 1242 SVID 1821 PCI SPEED Enable] C:\Users\123\0	Nesktop (FW \	191209_70_F2	18.bin	¥ _Ph	mware Info	F PW Che	di Enable	Function Tet	t 5.0 1.0 F USE 1. F Port 1. 200	13.1	2418121
Max									F	Signal Line Te	st	
Max Manual Setting Reg Setting PW Version Bu	Custor Cuetome	ner Informatio	Ion n (MAX 31) /ID Update	US82 Port1	US82 Port2 U	JS83 Port1 U	JS83 Port2	US83.1 Pert1	US83.1 Port2	Signal Line Te Fixture Test	TT Result	LT
Max Manual Setting Reg Setting PW Version U91209_70_F2_18 1	Custor Custors Dev Fun 0 0	ner Informati rr Informatio SSID S1 2142 E	lon n (MAX 31) /ID Update >21	US82 Port1	US82 Port2 U	1583 Port1 U	/583 Port2	US83.1 Port1	US83.1 Port2	Signal Line Te Fixture Test SLT Result	TT Result	0
Max Maxual Setting Reg Setting PWVVersion Bu 191209_70_972_18 1	Custor Custors Dev Fun 0 0	ner Informatio	ion	US82 Ports	US82 Port2 L	JS83 Port1 L	ISB3 Port2	US83.1Port1	USB3.1 Pert2	Signal Line To Fixture Test SLT Repult	TT Result	0

5. After burning the firmware successfully, check if the version number is

correct and restart the computer.

we INI Load INI	C:\Users\123\Desktop	PWVASM3142MPTool_	V1122\ASM3142MPTool.ini		Lock MP Tool	Debug Log	asmedi	a
Page Upgrade Test Page Upgrade Test Provide Enable Firmware Browser Sub_Sys SSID 1242 SVID 1821 PCI SPEED Enable Max] ::\Jsers\123'Desktop'i	FW\191209_70_F2_18	Lbin 💌	Pirmware Info	PW Check Enable	Function Test □ USB 2.0 □ USB 3.0 □ Port 1 Time Out(ms) □ Sig	0 F USB 3.1 F Port 2 200 gnal Line Test	
						E Po	xture Test	
Manual Setting Reg Setting 191209_70_F2_18	Customer Infor Customer Infor Dev Fun SSID 0 0 2142	mation Jation (MAX 31) SVID Update 1b21 PASS	USB2 Port1 USB2 Port	2 US83 Port1 US831	Port2 US83.1 Port3	US83. 1 Port2 S	RT Result TT Result	1.