

PRODUCT DATA SHEET PARTALL® Film #10

TNCE 1953	PARTALL® FIIM #10
	General Product Information
film forming materials. The dry PVA ites parts but is soluble in water. It polyester or epoxy resins and va	film is resistant to the solvents in the resin system used to make composis particularly recommended as a parting agent for separation between arious mold surfaces but may be used with most thermoset resins. Ended for use with resin or substrates containing water or giving off water
	om mold surface and is readily dissolved from molded parts and spray mposite casting processes PARTALL® Film #10 is used over wax or other Preparing Mold Surface
lacquer or similar coating and waxe but a good surface on plaster or wo Rough wood molds or plugs may be mold release wax to mold or plug su	m #10 porous molds (i.e., plaster or wood) should first be sealed with d. Composites grade sealers and fairing compounds are recommended ood may be obtained with automobile type primer-sealers and lacquers. adequately sealed with a number of coats of PARTALL® Paste #2. Apply affaces according to instructions and polish each coat to a shine. Choose /E® Mold Release Wax, or PARTALL® Hi-Temp Wax according to process — Directions for Use
PARTALL® Film #10 is ready to use	e as received and should not be diluted. Preferred application is with a
spraygun. Good results may be obtadraining excess PVA. Recommende	ained with a sponge applicator or paint brush or by dipping substrate and ed air pressure with HVLP spraygun is 22 - 24 PSI (1.5 - 1.7 BAR) at the aygun adjust air pressure to 60 - 90 PSI (4 - 6 BAR). Normal gun to
and allow each coat to dry comple PARTALL® Film #10. Do not begin mately 15 - 30 minutes per coat depended dry film thickness should be industrial type trash bag. 1 - 2 mils Film #10 will exhibit a white foamy a or contain runs when applied. If ap Make certain that PARTALL® Film #1 be very smooth and glossy when designed in the part of the	,
	Removing Part from Mold
The best procedure for separating	parts from a mold depends on the size and shape of the part. In most

The best procedure for separating parts from a mold depends on the size and shape of the part. In most cases a part can be lifted from the mold after loosening around the edges. Injecting compressed air between the part and mold at the edge is sometimes useful. On difficult or large parts it may be helpful to introduce water between mold and part to dissolve the PVA parting film helping to float the part free. PVA parting film generally comes off with the part and will need to be renewed on the mold for each part.

55 Gallon (208.2 liter) drum, 5 Gallon (18.9 liter) pail, and 1 Gallon (3.79 liter) bottle available in green or clear