

JIDEO INSTRUCTIONS



GEEKCLUB.COM



SMALL COMPONENTS



CLIPPING ELEMENTS RoHS

CERTIFIED



ADULT SUPERVISION



CHOKING HAZARD



LEAD FREE



THIS MIGHT HELP



FUN PCB




USING GLASSES WHEN SOLDERING

ASSEMBLE AND SOLDER THIS KIT IN A WELL-VENTILATED AREA


READ BEFORE FLIGH

FOR BEST QUALITY JOINTS, HEAT BOTH METAL PARTS WITH THE SOLDERING IRON IN QUICK SUCCESSION. ADD SOLDER BETWEEN THE METAL PARTS, DO NOT USE SOLDER ON THE ENTIRE PAD. KEEP SAFE ▶


NOTE:

















EACH PART IS MARKED WITH A LETTER AND NUMBER

THIS CODE INDICATES
THE PART'S LOCATION

THE LETTER CORRESPONDS TO THE BOARD. THE NUMBER SHOWS ITS LOCATION ON SAID BOARD









PROCEED STEP BY STEP FOLLOWING AN ASCENDING ORDER









READ BEFORE FLIGHT


MORE TIPS AND DETAILS
IN OUR ONLINE
INSTRUCTION VIDEO



WWW.GEEKCLUB.COM

COMPONENTS AND OTHER ELEMENTS_












NOTE:

- 1. DON'T WORRY IF YOU LOSE A FEW LEDS, WE'VE GOT YOU COVERED THERE ARE EXTRA DIODES IN THE KIT
- 2. MAKE SURE TO FOLLOW THE POLARITY (PINK) AND (GREEN) WHEN INSTALLING COMPONENTS. OTHERWISE, YOUR MODEL WILL NOT WORK.



READ BEFORE FLIGHT


FRONT



3.9"

▼ KEEP SAFE

RIGHT




7.1"




BACK


READ BEFORE FLIGHT





4.9"












































































MORE INFO NEXT PAGE


















MORE FUN STUFF ON OUR WEBSITE !!!
A QUESTION ? SOME COMMENTS ?



