

穿線方法

請確實按照圖示各種不同縫合情況穿線，錯誤之穿線將引起斷線、跳針及車縫不平坦等現象。(圖11)

THREADING

Follow the procedures shown in (Fig 9) for threading. Wrong threading may cause thread breaking, stitch skipping, puckering or unexpected sewing. (Fig. 11)

