

22

23

24

25

944ADPT6

944FCLPLT

90126A030

M8X30SOCHD

2

2

4

4

STIFFENER BRACKET

CLAMP PLATE BLADE

FLAT WASHER, M8, ZINC

BOLT, M8-1.25 X 30 SOC HD.ZINC

are known to fail catastrophically, even under street driving conditions. Porsche redesigned them in 1987 to resolve the problem. Using the earlier arms in competition and/or with other competition components will likely increase the stress on them and further increase the chances of their failure. We highly recommend either replacing them with a reliable aftermarket design, or having them properly reinforced, or inspecting them for cracks before EVERY race session.