



# MK10 'ATLAS' CT CONNECTIONS



## NOTES:

1. **6 AMP UP-STREAM PROTECTION MUST BE PROVIDED FOR POTENTIAL REFERENCES. (POT. FUSES)**
2. CT TEST BLOCK MUST BE INSTALLED.
3. ISOLATING SWITCH MUST BE INSTALLED BEFORE CT's.
4. NOTE POLARITY OF CT's.:  
i.e: P1 MUST FACE TOWARDS SUPPLY. P2 MUST FACE TOWARDS LOAD.  
S1 MUST BE CONNECTED TO INCOMING CURRENT ON METER. S2 MUST BE CONNECTED TO OUTGOING CURRENT (RETURN) ON METER.

BRIDGING LINK



## NOTE:

- A. BRIDGING LINK FITTED TO CT TEST BLOCK TO EARTH CURRENT RETURNS.  
C-PHASE RETURN CONNECTED TO EARTH.

**SUPPLY SIDE**  
(TRANSFORMER SIDE)

