



May 7, 2024

DASCOM Americas Announces Discontinuance of Twinax/Coax Connectivity Option on Various Printer Models.

DASCOM Americas announces discontinuation of Twinax/Coax Optional Connectivity for models 2810/2820/LA2810/LA2820 **effective immediately**. DASCOM will continue to support existing contracts and models utilizing the Twinax/Coax option, however, no new sales for the options will be accepted.

The reason for the discontinuation is limited on-hand stock of existing support options and the inability to provide economically-feasible new builds due to low demand and discontinuation of necessary components to complete new builds.

Part numbers affected by the discontinuation appear in the table below:

Part Number	Description
043882	Twinax, SCS
043883	Twinax, IPDS
043884	Coax, SCS
043885	Coax, IPDS
043887	Twinax, TN5250

For upgrade or conversion paths utilizing non-Twinax/Coax solutions, please contact DASCOM Americas technical support group at 877.434.1377, option 4.

Should you have questions on this announcement please contact Lance Clark DASCOM Americas Director of Printer Operations and Sales at lclark@dascom.com.