




Assembly Instruction




NO.	QTY.	LINEDRAWING	DESCRIPTION
(A)	8	 Ø7*50	
(B)	4		
(C)	1		
(D)	1		
(E)	2	 Ø4*22	
(F)	16		
(G)	18	 Ø3.5*14	
(H)	4		
(I)	12	 Ø3.5*35	
(J)	30	 Ø2*25	
(K)	3		




 Hammer and Screwdriver
 are not included !!





PARTS LIST





NO.	QTY.	LINEDRAWING	DESCRIPTION
①	1		
②	1		
③	1		
④	1		
⑤	4		
⑥	1		
⑦	1		


1



2




3



(F) 16 PCS



4



(B) 4 PCS



(D) 1 PCS



(E) 2 PCS



(K) 3 PCS



(G) 18 PCS



4 OF 4