



SERVICE BULLETIN # 017

DATE: 02/12/2022

PRODUCT LINE: 50mm Tail Union (950920)

SUBJECT:

REVISION	REVISION DESCRIPTION	BY	DATE
A	INITIAL RELEASE	DDaft	02/12/22

OVERVIEW:

Failure Description: Flash on the outside diameter of 50mm Tail Union. This fault makes it difficult to assemble the Tail Union to the Lock Nut (950919). The fault is in component bags packed from August 1st to December 1st.

Cause: Issue in the moulding process that was not picked up during routine inspections.

DISTRIBUTION RELEASE NOTES:

This Service Bulletin is to be made available to:

Fluidra - Internal	Fluidra - Export	Dealers	Warranty Agents	Trade Portal
<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>

An instance of Flash to the Outside Diameter of Tail Union (950920)



Actions

- In some instances, the flash must be removed before installation.
- This can be achieved by scraping or filing the flash from the outer diameter.
- **Do Not attempt to cut with a knife, as injury may occur.**

SERVICE BULLETIN