



Cranbrook Extra Treadles Option

Parts Lists

I. Adding 4 treadles to a 4-shaft, 6-treadle loom for T= 10 treadles

Parts: 16 tie-up cords
16 anchor pins
4 treadles

II. Adding 6 treadles to a 4-shaft, 6-treadle loom for T = 12 treadles

Parts: 24 tie-up cords
24 anchor pins
6 treadles
longer treadle rod (for loom made prior to 1999)

III. Adding 2 treadles to an 8-shaft, 10-treadle loom for T=12 treadles

Parts: 16 tie-up cords
16 anchor pins
2 treadles
longer treadle rod (for looms made prior to 1999)