

NOTE:

service can perform this task. Typical machine shop charge for such service \$60.00~\$100.00

and blow blended.

*Intake valve protrusion must be set to spec (1.100"~1.110") to allot for appropriate clearances. *Always double check <u>ALL</u> clearances.