

ESCORT® LASER SHIFTERS

Firmware Release Notes V2.12 & V1.12

What's New in Firmware V2.12 & V1.12

Cedar Electronics is happy to announce the release of version 2.12 and version 1.12 firmware for our laser shifters. Several minor improvements have been made in this release which will improve your laser shifter experience. This firmware update applies to:

- Max Ci 360
- Mac Ci
- iX Ci
- Max Ci Platform (relevant if shifters connected)
- Max Ci International (relevant if shifters connected)
- ZR5
- ZW5

Enhancements

- Improved performance rear laser shifters (ports 3 & 4)
- Fixed a laser gun identification bug
- Improved overall jamming performance

How to Distinguish Between V2 and V1 Laser Shifters

The V1 laser shifters and bridge box were changed in the fall of 2018 due to an end of life component. The performance is the same as V2. V2 laser shifters have a white stripe on the cable near the connector tip for the bridge box. V2 bridge boxes have a white dot on the bottom. Your installer will be able to look at your install to determine which version you currently have.

How to Get the Update

For consumers, please take your vehicle to an Authorized Escort Installer. For installers, you can find the update on Detector Tools Pro (<https://www.escortradar.com/pages/update-your-device>). There are two different links on the page depending on if you are using Windows or Mac OS.

Keep the Feedback Coming

We want to keep hearing from you! If you have feedback or suggestions on how to make our products even better, send an email to radarfeedback@cedarelectronics.com.