




- 1 Disconnect negative battery terminal.
- **2** Remove factory rear bumper
- **3** Remove rear body bolts & nuts





Mark, cut and remove factory rear crossmember and body mounts Remove rear body bolts & nuts





Now that the crossmember has been removed, proceed to body mounts



- **6** Grind the frame smooth for fitment
- Take the supplied jig and wrap it around the frame, lining it up flush with the end of the frame.





8 Use the jig to mark the frame for cutting. The same jig will be used for both sides



9 Cut the frame on the marked lines





Place the supplied end cap onto the frame.
You may need to further grind and smooth to ensure a proper fit



Tack end cap into place and check fitment, then fully weld on end cap





We recommend painting the crossmember before install. Use a piece of 1" tape to keep paint off the weld locations




Hold crossmember up and have a helper install the body bolts





14

Once installed, weld crossmember to frame





Install bumper using 2 factory bolts on each side of the frame plus three supplied bolts into the crossmember







