Pocket Digital Thermometer Model 314 3058302

To measure temperature with this unit, follow these simple instructions:

Select either the Fahrenheit or Celsius mode:

● With the unit 'OFF' press and continue to hold the ON/OFF button. The LCD will alternate between °F and °C.

● Release the ON/OFF button when desired measurement mode appears on the LCD.

Remove the protective sheath from the stem.

Press the ON/OFF button.

Insert stem into area or object to be tested. At least 1/2" of the stem must be inserted.

Warning: The stem is a sharp and pointed object which can be dangerous.

The Data Hold function is used by pressing the D-H button when taking a measurement. The Measurement will flash on the LCD when Data Hold is in use. To return to normal function, press and release the D-H button a second time.

Press the ON/OFF button to end operation, or the unit will automatically power off after 35 minutes.

$C\epsilon$

Specifications:
Range......... -58° to 300°F / -50° to 150°C
Resolution.................................... 0.1°F/C
Accuracy.................................. ±2°F, ±1°C
Sampling Time..................... 1.5 seconds
Battery.............................. 1.5 Volt Button
(Part No. AB13; SR44)

THIS INSTRUMENT is in compliance with
EN 50 081-1:1992, EN 50 082-1:1992,
IEC 801-2:1984, IEC 801-3:1984, IEC 801-4:1988

COMARK
A Fluke Company

Comark Instruments

Tel: (503) 643 5204
Fax: (503) 644 5859
Email: sales@comarkUSA.com
www.comarkUSA.com   Made in Korea