Motli LT® – Instruction Manual

- Charging Method: USB Lighter can be connected via USB-C to the computer and any other charger whose output voltage is DC 5.0±0.25V.

- Before first use, please connect to the charger and charge in full.

- Battery Charge time approx. 1-1.5 hrs.

Safety Instructions:

- Please do not exceed a 10-second ignition time.

- Please make sure the arc tips are free of debris before using.

- Please do not touch arc tips to skin.

- Keep lighter away from children.

- Keep the lighter away from high temperature.

- Keep the lighter away from water or other liquids.

- Do not stab or puncture or drop the lighter.

Arc Lighter Operating Instructions:

Power on/off

- Power on - press and hold the red power button until the green LED turns on

- Power off – press and hold the red power button down until the green LED shuts off.

- The lighter will automatically shut off after 60 seconds. The green LED will shut off, indicating that the power is off.

Igniting the lighter

- Power on the lighter, then press and hold the ignition button down. The lighter will stay lit for approximately 10 seconds while the ignition button is pressed down.

Charging the lighter

- Plug the USB-C charge cable into the lighter. The green LED will flash while charging and stay solid when the lighter is fully charged.

Charge me

- When pressing and holding the power button to power the lighter on, the green light will flash three times, indicating that the lighter needs to be charged.

User Lighting Tips

- For best results, begin by holding the lighter 1 inch away from the target.

- To light the target: Push and hold the ignition button down to ignite the flameless electric arc, moving the arc toward the target to light.

Traveling with your USB Lighter: Please make sure to check with your local airport on their policies for Lithium-Ion Batteries.

Warranty: All products have a 30-Day Replacement Warranty against all factory defects.