Dear Valued Customer,

Due to component issues at Honeywell our traditional horn/strobes (CM-7004) are temporarily unavailable.
CO2Meter has worked with Honeywell to temporarily provide us an alternate horn/strobe (CM-7004-2).

The differences with this temporary horn/strobe are:

- The horn and strobe alert together
- The "CO2" sticker will be black
- Detailed instructions about installation and precise settings will be provided

CM-7000 System Settings Note:

The "STROBE" switch on the tablet settings page controls the horn and strobe function on the CM-7004-2. This switch MUST be toggled to the "ON" position for the system to alarm properly.

If Alarm 1 settings are altered from the factory settings you must also toggle the "AUDIO" and "STROBE" on as well.

Please contact CO2 Meter Technical support if you have any questions regarding this product change or required system settings.

Thank you,

CO2 Meter