wowhelperco

2023

January
S M T W T F S
1 2 3 4 5 6 7
8 9 10 11 12 13 14
15 16 17 18 19 20 21
22 23 24 25 26 27 28
29 30 31

February
S M T W T F S
1 2 3 4
5 6 7 8 9 10 11
12 13 14 15 16 17 18
19 20 21 22 23 24 25
26 27 28

March
S M T W T F S
1 2 3 4
5 6 7 8 9 10 11
12 13 14 15 16 17 18
19 20 21 22 23 24 25
26 27 28 29 30 31

April
S M T W T F S
1
2 3 4 5 6 7 8
9 10 11 12 13 14 15
16 17 18 19 20 21 22
23 24 25 26 27 28 29
30

May
S M T W T F S
1 2 3 4 5 6
7 8 9 10 11 12 13
14 15 16 17 18 19 20
21 22 23 24 25 26 27
28 29 30 31

June
S M T W T F S
1 2 3
4 5 6 7 8 9 10
11 12 13 14 15 16 17
18 19 20 21 22 23 24
25 26 27 28 29 30

July
S M T W T F S
1
2 3 4 5 6 7 8
9 10 11 12 13 14 15
16 17 18 19 20 21 22
23 24 25 26 27 28 29
30 31

August
S M T W T F S
1 2 3 4 5
6 7 8 9 10 11 12
13 14 15 16 17 18 19
20 21 22 23 24 25 26
27 28 29 30 31

September
S M T W T F S
1 2
3 4 5 6 7 8 9
10 11 12 13 14 15 16
17 18 19 20 21 22 23
24 25 26 27 28 29 30

October
S M T W T F S
1 2 3 4 5 6 7
8 9 10 11 12 13 14
15 16 17 18 19 20 21
22 23 24 25 26 27 28
29 30 31

November
S M T W T F S
1 2 3 4
5 6 7 8 9 10 11
12 13 14 15 16 17 18
19 20 21 22 23 24 25
26 27 28 29 30

December
S M T W T F S
1 2
3 4 5 6 7 8 9
10 11 12 13 14 15 16
17 18 19 20 21 22 23
24 25 26 27 28 29 30
31

Our social media

Instagram
Facebook
Pinterest

@wowhelperco

https://www.pinterest.com/PetsHelperCo/

https://www.facebook.com/wowhelperco/

Cat's house

Email: petshelperco@gmail.com

Etsy

| A	B	C
1pc	1pc	2pcs
D	E	F
1pc	6pcs	1pc
G	H	
8pcs	1pc	

Video assembly

STEP 1

1. Take the elements A, B, D, E.
2. Insert parts (E) into the slots of parts (A) and (B)
3. Fasten the parts with (G) screws as shown in picture using the hex key (H)

STEP 2

1. Operation 1. Screw part (C) as shown in the figure.
!!! - Pay attention to the position of the bar.
2. Operation 2. Place part (F) between the plank.
!!! - Pay attention to the position of the round hole.
3. Operation 3. Pressing part (F) to part (A), cover with part C as shown in the figure.
!!! - Pay attention to the position of the bar at part C.
4. Fasten the parts with (G) screws as shown in picture using the hex key (H).

oper.3
oper.2
oper.1