Kestrel® Interface
Communicator Software Instructions

Thank you for purchasing the Kestrel Interface and Communicator Software. This system will upload the stored data from your Kestrel Meter to a computer for long–term storage, in–depth analysis or detailed charting. This system works with any Kestrel 4000 series model.

BEFORE STARTING
What's in the Box:
- Interface Cradle–Kestrel Meter snaps into the cradle for optical communication
- A Serial or USB Cable–plugs into the interface and your computer

What You'll Need:
- A PC with an available Serial or USB port
- Windows XP, Windows 7 or Windows 8
- A Kestrel 4000 series Meter

INSTALLING THE SOFTWARE
- Visit www.nkhome.com/support/pdfs.html.
- Scroll down to Kestrel section, then Software.
- If USB, download USB driver first and install.
- Download Kestrel Communicator Software and save the file to your desktop.
- Double-click the Kestrel icon and run the software to install.

NK

NIELSEN-KELLERMAN

21 Creek Circle | Boothwyn | PA 19061 | **P** 610- 447-1555 | **F** 610- 447-1577 | www.nkhome.com